Enrollment:

Purchaser Name: Navdeep Singh Kaul

Phone Res:

Phone Bus: (647) 629-7980 Closing Date: August 18, 2022 Inspector: Gisella Fiore

HOMES

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 118A / 1

Plan: Address: Municiaplity:

Inspection Date: August 12, 2022

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

EXTERIOR		
GARAGE DOORS	NOT INSTALLED	 
DECK	PLANKS NOT INSTALLED AT BEDROOM BALCONY	 
RAILING	NOT INSTALLED AT FRONT PORCH	 
PORCH	DENT ON SIDING CEILING AT FRONT PORCH	 
	CHIP ON FRONT PORCH	 
	SCRATCH ON TOP TRIM ABOVE OPERATING DOOR	 
LIVING ROOM		
WINDOWS	SCRATCH / CRACK ON BALCONY SLIDING GLASS	 
KITCHEN		
=	CHIP ON LEFT ISLAND GABLE	 
CABINETS	CHIP INSIDE LOWER CABINET RIGHT OF FRIDGE AT GABLE	 
	CHIP / CRACK INSIDE UPPER CABINET AT LEFT GABLE LEFT OF HOOD FAN	 
FLOORING	REMOVE MARKS FROM FLOOR BELOW SINK ISLAND	 
FOYER/HALL		
STAIRS	CHIP ON 3RD RISER AT STAIRS TO 1ST LANDING TO 2ND FLOOR	 
	CHIP ON INSIDE STRINGER LEFT SIDE AT STAIRS TO BASEMENT BY 1ST TREAD	 
FLOORING	CHIP ON 2ND HARDWOOD PLANK INFRONT OF STAIRS TOO 2ND FLOOR	 
	SCRATCH ON 3RD PLANK FROM KITCHEN INFRONT OF STAIRS	 
	CHIP ON 6TH AND 7TH PLANK AT FLOOR INFRONT OF BASEMENT STAIRS	 
WALLS	BOWED WALL RIGHT SIDE OF MAIN HALL	 
FRONT DOORS	CHIPS ON OPERATING DOOR AT SIDE ABOVE HINGE	 
MASTER ENSUITE BATH		
VANITY CABINETS	CHIP INSIDE LOWER LEFT CABINET AT BOTTOM GABLE	 

Enrollment:

Phone Res:

Purchaser Name: Navdeep Singh Kaul

Phone Bus: (647) 629-7980

Closing Date: August 18, 2022

ZANCOR

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 118A / 1

Plan: Address:

Municiaplity:

Inspector	: Gisella Fiore	Page 2 of 2	Inspection Date:	August 12, 2022	
MASTER ENSUITE BATH					
ELECTRICAL/LIGHTING	SECURE POT LIGHT AT CEILING IN SHOWER				
MASTER BEDROOM					
WINDOWS	CRACK ON RIGHT FIXED GLASS				
FAMILY ROOM					
FLOORING	CHIP ON 9TH PLANK FROM LEFT WALL AT ELE	ECTRICAL OUTLET			
POWDER ROOM					
NOTE:	HANDLES NOT INSTALLED AT VANITY				
	CHIP ON INSIDE GABLE RIGHT SIDE AT VANIT	Y AND BACK PANEL CRACK	KED		

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. \* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Navdeep Singh Kaul Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Gisella Fiore Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature 2022/08/12 August 12, 2022 Date (YYYY/MM/DD)