Enrollment:

Purchaser Name: Papa, Kwaku Oppong

Dominique, La Nea, Oppong

Phone Res:

Phone Bus: (416) 996-3988 Closing Date: August 25, 2022 Inspector: Gisella Fiore

HOMES

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 18 (Block 3) / 1

Plan: Address: Municiaplity:

Inspection Date: August 18, 2022

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

LARGE CRACK ON 3RD TREAD FROM 3RD FLOOR TOO 2ND FLOOR STAIRS / CHIP ON INSIDE		
STRINGER AT STAIRS FROM MAIN FLOOR TOO 1ST FLOOR		
VARNISH REQUIRED AT OUTSIDE STRINGER BY 2ND TREAD AT STAIRS TO 3RD FLOOR		
NOT INSTALLED AT REAR OF HOME		
NOT INSTALLED AT MASTED BEDROOM BALCONY		
EAVESTROUGH NOT INSTALLED AT FRONT PORCH		
NOT INSTALLED		
CHIP ON 3RD PLANK FROM POWDER ROOM WALL INFRONT OF STAIRS		
DENT ON 3RD PLANK FROM LEFT TRIM AT ENTRANCE TO SURVERY FROM KITCHEN.		
SCRATCH ON PLANK LEFT OF ISLAND		
SMALL CHIP ON UPPER LEFT DOOR RIGHT OF HOOD FAN		
CHIP ON UPPER LEFT DOOR AT SURVERY INSIDE		
CHIP ON RIGHT SIDE EDGE AT COUNTERTOP		
INSPECT BLACK MARK ON TUB FRONT		
ADJUST DOOR NOT LATCHING		
SEAM IN CEILING LEFT OF FIREPLACE		
	STRINGER AT STAIRS FROM MAIN FLOOR TOO 1ST FLOOR VARNISH REQUIRED AT OUTSIDE STRINGER BY 2ND TREAD AT STAIRS TO 3RD FLOOR NOT INSTALLED AT REAR OF HOME NOT INSTALLED AT MASTED BEDROOM BALCONY EAVESTROUGH NOT INSTALLED AT FRONT PORCH NOT INSTALLED CHIP ON 3RD PLANK FROM POWDER ROOM WALL INFRONT OF STAIRS DENT ON 3RD PLANK FROM LEFT TRIM AT ENTRANCE TO SURVERY FROM KITCHEN. SCRATCH ON PLANK LEFT OF ISLAND SMALL CHIP ON UPPER LEFT DOOR RIGHT OF HOOD FAN CHIP ON UPPER LEFT DOOR AT SURVERY INSIDE CHIP ON RIGHT SIDE EDGE AT COUNTERTOP INSPECT BLACK MARK ON TUB FRONT ADJUST DOOR NOT LATCHING	STRINGER AT STAIRS FROM MAIN FLOOR TOO 1ST FLOOR VARNISH REQUIRED AT OUTSIDE STRINGER BY 2ND TREAD AT STAIRS TO 3RD FLOOR NOT INSTALLED AT REAR OF HOME NOT INSTALLED AT MASTED BEDROOM BALCONY EAVESTROUGH NOT INSTALLED AT FRONT PORCH NOT INSTALLED CHIP ON 3RD PLANK FROM POWDER ROOM WALL INFRONT OF STAIRS DENT ON 3RD PLANK FROM LEFT TRIM AT ENTRANCE TO SURVERY FROM KITCHEN. SCRATCH ON PLANK LEFT OF ISLAND SMALL CHIP ON UPPER LEFT DOOR RIGHT OF HOOD FAN CHIP ON UPPER LEFT DOOR AT SURVERY INSIDE CHIP ON RIGHT SIDE EDGE AT COUNTERTOP INSPECT BLACK MARK ON TUB FRONT ADJUST DOOR NOT LATCHING

Enrollment:

Purchaser Name: Papa, Kwaku Oppong

Dominique, La Nea, Oppong

2022/08/18

Phone Res:

Date (YYYY/MM/DD)

Phone Bus: (416) 996-3988
Closing Date: August 25, 2022
Inspector: Gisella Fiore

ZANCOR HOMES

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 18 (Block 3) / 1

Plan: Address: Municiaplity:

Inspection Date: August 18, 2022

LAUNDRY ROOM			
NOTE:	FILL NAIL HOLES AT WOOD TO LAUNDRY		
POWDER ROOM			
SINK/FAUCET/PLUMBING	TOILET SEAT NOT INSTALLED		
BASEMENT			
NOTE:	BASEMENT DOOR CRACKED AT HINGE		
	HOLE IN CONCRETE		
	FLOOR DRAIN NOT INSTALLED		

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Papa, Kwaku Oppong Dominique, La Nea, Oppong Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Gisella Fiore Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature

August 18, 2022