

LOI #	-	The Treffis listed below Were released to the hor
	フノ	Molad
	-	were
ı		released
Si		to th
Site/Phase:		e homeowne
Caledon	,	wner (s) of

The above items were received on this K day of	N/A Other	N/A Recycling and Green Bins	☐Homeowner Manual	☑House and Garage Door Keys
<b>A</b> day of				
Avgest				

CALEDON

Purchaser

Purchaser

,2022

Purchaser Name: Jaskaran Singh Dhaliwal Kirandeep Kaur Dhaliwal

Phone Res:

Phone Bus: (905) 782-3441 Closing Date: May 26, 2022 Inspector: Gisella Fiore

HOMES ANCOR

Vendor / Builder:
Project: Zancor Homes (Caledon) Ltd.
Lot / Phase: 117A / 1
Plan:

Page 1 of 2 Municiaplity: Inspection Date: August 17, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS), Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING Windows, side lights and other glazing. Window and door screens Bathtub sinks and tollets Bathroom accessories if provided Minrois, counter tops and cabinetry Flooring (hardwood, vinyl, ceramic tiles, carpeting) Interior finished and trim carpentry

## Hot water heater, if provided (not rental) Exterior finished, driveways, walkways, decks and landscaping

- OPERATING CONDITION

  Windows, interior and exterior doors, Door locks
  Faucets: Kitchen, bathroom, laundry room
  Exhaust fans (kitchen, bathrooms) if provided
  Electrical outlets and fixtures
  Gas fireplaces, incl.circulation fans, if provided
  Heat Recovery Ventilation system, if provided
  Heating system
  Hot water heater, if provided (not rental)
  Air conditioning system, if provided and if conditions permit

SHOWER ENCLOSURE	SHOWER GLASS NOT INSTALLED
VANITY CABINETS MIRROR	SILICONE REQUIRED INSIDE SHOWER MAIN AND MASTER HANDLES NOT INSTALLED ON BANK OF DRAWERS AT VANITY MIRRORS NOT INSTALLED THROUGHOUT
FAUCETS/PLUMBING	LEFT SINK NOT HOLDING WATER
MAIN BATHROOM	
SHOWER ENCLOSURE	SHOWER GLASS NOT INSTALLED
COUNTERTOPS	CHIP ON RIGHT SIDE COUNTERTOP AT EDGE
	INSPECT SCRATCH LEFT OF RIGHT SINK
KITCHEN	
CABINETS	MISSING CABINETS NOT INSTALLED AT HOOD FAN AS PER DRAWINGS
	CHIP ON VALANCE BELOW CORNER LEFT OF STOVE
	BLACK MARKS ON UPPER RIGHT DOOR RIGHT RIGHT OF HOOD FAN
BEDROOM #3	
WINDOWS	ADJUST OPERATING WINDOW CANNOT OPEN
BEDROOM #4	
WALLS	HOLE IN STIPPLE LEFT OF LIGHT
EXTERIOR	
PORCH	INSPECT SLOPE AT DECORATIVE BALCONY NOT DRAINING
NOTE:	REMOVE SPLATTER FROM FRONT DOOR
	MISSING VENT RIGHT SIDE OF HOUSE
SHINGLES GARAGE DOORS	INSPECT FLASHING RIGHT OF UPPER RIGHT WINDOW ABOVE GARAGE STICKING OUT CHIP ON LEFT GARAGE FRAME

Enrollment: Purchaser Name: Jaskaran Singh Dhaliwal Kirandeep Kaur Dhaliwal

Phone Res:
Phone Bus: (905) 782-3441
Closing Date: May 26, 2022
Inspector: Gisella Flore

HOMES

Vendor / Builder:
Project: Zancor Homes (Caledon) Ltd.
Lot / Phase: 117A / 1
Plan:
Address:
Municlapiliy:
Inspection Date: August 17, 2022

Date (YYYY/MM/DD)	Designate's Name (print)		Purchaser's Name (print)	Jaskaran Singh Dhaliwal	I have inspected my new home	THE COMPLETED PRE-DELIVERY INSPECTION IS A F A REFERENCE FOR FUTURE WARRANTY REQUESTS.  * Purchasers or owners who intend to designate someor designate to sign this form on their behalf.	NOTE:	BASEMENT	t t	LAUNDRY ROOM	WINDOWS		FLOORING	DINING ROOM	FRONT DOORS	O A A A	POTENTALL	DOVEDO	EVICENCE		inspector:
2022/08/47	Designate's Signature		Purchaser's Signature	P P	I have inspected my new home and I agree that the description of the items listed on this form are eccurate.	ERY INSPECTION IS A FORMAL RECORD OF- WARRANTY REQUESTS. Yend to designate someone to conduct the PDI in their behalf.	FILL HOLE IN FLOOR		REMOVE RED MARKS ON COUNTERTOP EDGE BEHIND SINK		SCREEEN BOWED IN LIVING ROOM AS WELL	DUCT INSIDE VENT TO BE ADJUSTED CANNOT FIT VENT COVER	CHIP ON 19TH FLOOR FROM LEFT WALL INFRONT OF AIR RETURN		SCREW COVER NOT INSTALLED	CHIP ON 1ST TREAD ABOVE LANDING AT STAIRS TO 2ND BY 4TH TREAD AT STAIRS TOO 2ND FLOOR 1ST LANDING		MOTAR REQUIRED AT BRICK RIGHT SIDE OF HOUSE BY VENT		Inspector: Gisella Fluid	Cicalla Flavo
	Inspector's Name (print)	Gisella Flore	Purchaser's Name (print)	Kirandeep Kaur Dhaliwal	ed on this form are accurate.	THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.  * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.			DGE BEHIND SINK		EL	NOT FIT VENT COVER	NFRONT OF AIR RETURN			CHIP ON 1ST TREAD ABOVE LANDING AT STAIRS TO 2ND FLOOR / CHIP ON INSIDE STRINGER BY 4TH TREAD AT STAIRS TOO 2ND FLOOR 1ST LANDING		OF HOUSE BY VENT		rage z or z	
	Inspector's Signature	The same of the sa	Purchaser's Signature			R TAKES POSSESSION IT WILL BE USED AS		And the second s		The same of the sa				TEXTON AND TOTAL T		ER	To a constant			Inspection Date: August 17, 2022	Municiapity:
							-	_	<u></u>	_			_	_		L		L			

Date (YYYY/MM/DD)

2022/08/17

August 17, 2022