

ME
2 Kicks BLACKWOOD

11

5 Kicks Storm

1-45 shelf

1-90 shelf

Kitchen

- Over Fridge cabinet inside edge very rough
- Kicks Missing
- Lower doors chipped throughout (inside/outside)
- Lower right cabinet shelf chipped.
- 2 upper right cabinets shelves chipped
- Island doors chipped (inside)
- Chip on short side of Island.
- Red residue on right countertop.

Pantry

- Kick missing (Sink side)
- Lower doors chipped (marked)
- Red residue on countertop.
- upper shelves chipped
- Long uppers inside edge very rough
- Long lowers

Shared Ensuite

- Left cabinet chipped inside
- Right cabinet doors chipped inside

Master Ensuite

- Kick missing
- Right inside edge under both sinks rough
- Left cabinet doors chipped
- middle cabinet chipped
- Right cabinet doors chipped (inside)
- Red residue on countertop
- chip on right side of backsplash

Ensuite

- Red residue on countertop.
- chip in cabinet

ALL
DONE



Prest

All Components

Aug 26
27458B
Key Access

Customer: Zancor Homes (Wasaga) Site: Wasaga
Ltd.

Lot: 11

Notes: ✓ Master Ensuite:
-Supply & Install (1) Shelf for 800x535 Vanity Cabinet

Done

All above service items have been completed.

Date Completed: 26 Aug, 2022

New Image Kitchens Representative:

Index

Homeowner Representative:

Client Representative:

Name

Signature

08-10-2022



CHARLES

All Components

Key Access
27458A

Aug 8

Customer: Zancor Homes
(Caledon) Ltd.

Site: Wasaga

Lot: 11

Notes:

KITCHEN:

- ✓ -Supply & Install (5) Kitchen Kicks (Euro-Storm)
- ✓ -Supply & Install (1) Shelf for upper cabinet 45cm
- ✓ -Supply & Install (1) Shelf for upper cabinet 90cm

MASTER ENSUITE:

- ✓ -Supply & Install (2) Vanity Kicks (Euro-Blackwood)

1 shelf for vanity

~~1201~~

~~1402~~

~~1382~~

~~1380~~

2522

All above service items have been completed.

Date Completed: _____

New Image Kitchens Representative:

Homeowner Representative:

Client Representative:

Name

Signature