

116 priet

Aug. 26/22

Kitchen Q.C. Bumpers

key
Access

Kitchen

Done

- Cabinet above Fridge • Rough inside edges
- upper - Cabinet right of Fridge • Rough inside edges
- Upper corner cabinet • Shelf chipped
- Upper left of stove • Rough inside edges
 - Chip on shelf
- Upper right of stove • Glue inside
- Red residue on backsplash
- Lower right of Fridge • Shelf chipped
- Panel @ left of stove damaged/chipped
- Panel @ right of stove chipped
- Lower right of stove • chipped
 - Shelf chipped
- Cabinet under sink chipped.

Master Ensuite

- Left cabinet Cracked/Chipped inside
- Rough inside edge
- Right cabinet • Chipped
 - Rough inside edge
- Red residue on backsplash
- Doors missing Bumpers

Main Bath

- Red residue on backsplash
- Cabinet chipped

Laundry

- Red residue on backsplash