



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W166560
Pack Slip:198442

Service Date: Sep 09, 2022

Priority: Normal Status: SCHEDULED

BUILDER

Customer:	N000508	City:	WHITBY	Received:	Aug 31, 2022
Name:	ZANCOR WHITBY	Service Phone(s):		Time:	AM
Service Fax:		Site Phone:		Order:	D374345-1
Site Fax:		Lot#:	BLK 8 - 47	Phase:	PH1

RESIDENT INFORMATION

Home Owner Name:	GABRIELLA, R KOVARI	Address:	
Home Phone(s):		Work Phone(s):	
Cell Phone(s):	416-414-8413	Email(s):	ellakovari@gmail.com

LINKED ORDER INFORMATION (D374345-1)

Customer:	N000508 ZANCOR WHITBY	Lot #:	BLK 8 - 47
Model:	TH-1	Phase:	PH1

SERVICE INSTRUCTIONS

EXTERIOR- PORCH-CHIP ON MULIN AT EXTERIOR REAR PATIO

EXTERIOR- GENERAL- ITEM #1 ENTRANCE TO HOME HAS DEEP SCRATCHES ON DOOR FRAME. MORE THAN ONE SPOT AS PICTURED

EXTERIOR- GENERAL- ITEM #71- SCRATCHED FRONT DOOR FRAME ON MORE THAN ONE SPOT SEE PHOTO

EXTERIOR- GENERAL- ITEM #74- DOOR FRAME OF MASTER BEDROOM BALCONY BADLY CRACKED CHIPPED

EXTERIOR- GENERAL- ITEM #78 DENT IN METAL FRAME ABOVE PORCH AND CHIP IN PAINT

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
20	BUCKINGHAM PURCH. PATIO DOOR ext cladding	REC	OTHER RPLCMNT PARTS	71.5 X 95.5	BK 61316 RIGHT BUCKINGHAM PURCH. PATIO DOOR	1
50	BUCKINGHAM PURCH. PATIO DOOR vinyl cladding	MB	OTHER RPLCMNT PARTS	71.5 X 81.5	BK 61316 LEFT BUCKINGHAM PURCH. PATIO DOOR	1
90	DOOR JOIN 2 PART vinyl cladding	ENT	OTHER RPLCMNT PARTS	52.5 X 97.75	BK 61316 FJ	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:


Cause:

Solution:

Date Completed: SEP 08, 2022

Approved: 

Time: _____

Service Signature: 
RAY

Date Completed: Sept 9 2022

Homeowner Signature: [Signature]
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: SEP 9/22

Trade &/or Service Tech
Signature: [Signature]


Print Name: REY

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Now Towns In Brooklin - Phase: 1 - Lot: Unit 47 (Block 8)

**148271 - 1 - PORCH~CHIP ON MULIN AT
EXTERIOR REAR PATIO**





Zancor Homes (Parkview) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 30Jun22

Address:

Location: Now Towns In Brooklin - Phase: 1 - Lot: Unit 47 (Block 8)

Today's Date: 31Aug22

Contact(s): Gabriella, R Kovari - Cell: (416) 414-8413 - (ellakovari@gmail.com)

Email: ellakovari@gmail.com

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
148271	PDI	EXTERIOR- PORCH-CHIP ON MULIN AT EXTERIOR REAR PATIO		06Sep22 /am	GK-
149725	30-Day	Exterior- General- Item #1 Entrance to home has deep scratches on door frame. More than one spot as pictured		06Sep22 /am	GK
149795	30-Day	Exterior- General- Item #71- Scratched front door frame on more than one spot see photo		06Sep22 /am	GK.
149798	30-Day	Exterior- General- Item #74- door frame of master bedroom balcony badly cracked chipped		06Sep22 /am	GK
149802	30-Day	Exterior- General- Item #78 Dent in metal frame above porch and chip in pain		06Sep22 /am	NOT XIEUMAX CONCERN