Enrollment:

Phone Res:

Purchaser Name: Ramraj Das

Phone Bus: (416) 832-4153

Closing Date: May 12, 2022

Inspector: Gisella Flore

ZANCOR

Vendor / Builder:

Project: Zancor Homes (Wasaga) Ltd.

Lot / Phase: 31 / 1 Plan:

Address: Municiaplity:

Page 1 of 2

Inspection Date: August 30, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and tollets
- · Bathroom accessories if provided
- · Mirrors, counter tops and cabinetry
- · Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- · Hot water heater, if provided (not rental)
- · Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- · Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- · Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- · Air conditioning system, if provided and if conditions permit

EXTERIOR			0
GARAGE DOORS	NOT INSTALLED	V	100
PAINT	NOT COMPLETE AT GARAGE FRAMES		KO
DECK	NOT INSTALLED AT REAR	_X	Name :
FOYER/HALL		1	
STAIRS	VARNISH REQUIRED AT RISER BELOW NOSING AT STAIRS TO MUD ROOM AND BELOW NOSING AT 2ND FLOOR		PD_
	1) CHIP ON 5TH TREAD BY PICKET AT STAIRS FROM MAIN FLOOR TOO 2ND FLOOR 2)CHIP ON OUTSIDE STRINGER AT STAIRS TOO 2ND FLOOR 3) CHIP ON 5TH AND 6TH TREAD AT STAIRS FROM MUD ROOM TOO MAIN FLOOR 4) CRACK AT INSIDE STRINGER BELOW NOSING AT STAIRS FROM MUD ROOM TO MAIN FLOOR		_ED_
KITCHEN		/	- 2
NOTE:	WATER LINE FOR FRIDGE NOT INSTALLED AS PER EXTRAS	1/	ED.
MASTER ENSUITE BATH			
NOTE:	SCRATCH ON MARBLE SURROUND LEFT OF DOOR BY HINGE		RO
MAIN BATHROOM		/	1521
VANITY CABINETS	KICKPLATE NOT INSTALLED	V	121)

Homeowner Signature. Motor the (Rohan Dass)

The Homeowner acknowledges and accepts that all initialed work has been completed in a workman like manner to their satisfaction.

ADD
- RIGHT GARRGE DOOR - DENT @ TOP PANEL - ABBEY.
- FRONT DOORS - PAINT THIN & TUP FRAMES PT & ZANCOR
- SILICONE TOP OF MARBLE @ RIGHT OF TUB



Site: WASAGA BEACH
Phase: SHOREUNE POINT
The item listed below was released to the Homeowners of Lot #
Dyson Vacuum
*Zancor Homes is not responsible for warranty claims or defects of Dyson products
The above item was received on 12 day of 500000000000000000000000000000000000
ROHAN DASS ON BEHALF OF RAMPAJ DAS Homeowner



The items listed below were released to the homeowner(s) of

Lot #Site/Phas	se:Shoreline Point
√ House and Garage Door Keys	
√ Homeowner Manual (given at PDI)	
N/A Recycling and Green Bins	
N/A Other	
The above items were received on this day	y of SEPTEMBER, 2022
Malion Jay	
Purchaser KAWAJOA	Purchaser