

The items listed below were released to the homeowner(s) of

| House and Garage Door Keys Homeowner Manual N/A Recycling and Green Bins N/A Other The above items were received on this 16 day of 20 as in a | Site/Phase: INNISFIL. of SEPT 2022 |
|---|-------------------------------------|
| he above items were received on this 16 day of Opasins | SEPT , 2022 |
| Purchaser | Purchaser |

Outstanding Deficiencies Belle Aire Shores - Phase: 3 - Lot: 32W

| | | | | | / | 1 | | |
|---------|-------------------|------------------------|-----|---------------------------------------|--|----------------|------|-----------------|
| | | NoAppoint. | Add | Icon Plumbing & Heating 150033 | MASTER ENSUITE BATH- COUNTERTOPS~PLUMBING NOT COMPLETE AT SINK | | PDI | 13Sep22 |
| 110 | ** | NoAppoint. | Add | <u>AV</u> <u>Classic</u> 150032 | BEDROOM 2 ENSUITE- FLOORING~CHIPPED TILE AT ENTRANCE TO BATHROOM FROM 2ND BEDROOM | 10 F | PDI | 13Sep22 |
| | | NoAppoint. | Add | Quality Rugs Canada LTD. 150031 | BEDROOM #2- FLOORING~ADJUST CARPET SHIM | 9 | PDI | 13Sep22 |
| | | NoAppoint. | Add | Perfect Touch Painting 150030 | FOYER/HALL- STAIRS~TOUCH UP TREAD BELOW NOSING AT 2ND FLOOR SCRATCHED ? | 8 | PDI | 13Sep22 |
| | | NoAppoint. | Add | Newmar 150052 | FOYER/HALL- FRONT DOORS~LARGE GAP LEFT DOOR | 7 | PDI | 13Sep22 |
| | | MoAppoint. | Add | New Image Kitchens 150029 | KITCHEN- CABINETS~CHIP INSIDE LOWER LEFT CABINET AT ISLAND AT GABLE | 6 | PDI | 13Sep22 |
| | | NoAppoint. | Add | New Image Kitchens 150051 | KITCHEN- CABINETS~CHIP ON UPPER RIGHT CABINET LEFT OF HOOD FAN / CHIP ON LOWER LEFT DOOR AT SURVERY LEFT DOOR | V ₁ | PDI | 13Sep22 |
| | × | A. a.s. No Appoint. | Add | Newmar 150050 | KITCHEN- WINDOWS~SCREEN X DOOR NOT INSTALLED AT SLIDING DOOR | 4 | PDI | 13Sep22 |
| | | NoAppoint. | Add | Newmar 150028 | DINING ROOM- WINDOWS~SETTLEMENT CRACK AT RIGHT FIXED GLASS IN DINNING | w | PDI | 13Sep22 |
| 7 | _ | NoAppoint. | Add | Perfect Touch Painting 150027 | EXTERIOR- PAINT~NOT COMPLETE AT PEEK ABOVE ROOF | 2 | PDI | 13Sep22 |
| | 1 | No. | | | EXTERIOR- NOTE:~UNABLE TO CLOSE ELECTRICAL PLUG RIGHT OF FRONT DOOR | _ | PDI | 13Sep22 |
| Initial | Item Completed | Add Appointment | 7 | Trade Assigned | Deficiency Description | Number | Type | <u>Reported</u> |
| | | | | | | | | |

Exterior Guage door

| Homeowner Signature: | |
|----------------------|--|
| ure: | |
| | |
| | |
| | |
| | |
| | |

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

| Lancor Service Technician: | Date:_ |
|----------------------------|--------|
| | |