Enrollment:

Purchaser Name: Amit Kumari

Ojasvi Kumari

Phone Res:

Filolie nes.

Phone Bus: (647) 991-8652 **Closing Date:** September 22, 2022

Inspector: Gisella Fiore Page 1 of 2

ANCOR

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 112A / 1 Plan:

Address: Municiaplity:

Inspection Date: September 20, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

LAUNDRY ROOM		
CABINETS	HOLE CUT OUT TOO LARGE AS PER HOMEWONER SIDE GABLE FOR HOT WATER TOO WASHER	
BEDROOM #3		
WINDOWS	BOWED SCREEN	
BEDROOM 4 ENSUITE		
MIRROR	NOT INSTALLED	
VANITY CABINETS	CHIP AT BOTTOM GABLE RIGHT SIDE BELOW SINK	
	CHIP INSIDE LOWER RIGHT CABINET	
BEDROOM #2		
NOTE:	CATHEDRAL CEILING LEFT SIDE STIPPLE LOWER THEN RIGHT SIDE	
	SEAM IN STIPPLE RIGHT OF CLOSET	
FOYER/HALL		
STAIRS	FILL NAIL HOLES AT NOSING AT 1ST LANDING TOO 2ND FLOOR	
	NOSING AT FRONT ENTRANCE RAISED	
	DAMAGE ASTRICAL AT FRONT PORCH AND ABOVE OPERATING DOOR	
FLOORING	SMALL SCRATCH ON 1ST PLANK BY NOSING AT 1ST LANDING TOO 2ND FLOOR	
ELECTRICAL/LIGHTING	ROUGH IN FOR ALARM KEY PAD NOT COMPLETE	
KITCHEN		
CABINETS	CHIP ON UPPER LEFT CABINET LEFT OF FRIDGE	
	CHIP ON LET SIDE OF BUILT IN CABINET	
	CHIP ON LOWER RIGHT CABINET DOOR AT PANTRY RIGHT OF STOVE 2) CHIPS ON GARBAGE DRAWER	
	ADJUST GARBAGE DRAWER SLANTED LEFT	
NOTE:	AS PER HOMEOWNER SPEAK WITH SIMONE IF TILE BACKSPLASH IS REQUIRED TO INSTALLED RIGHT OF SINK NOT ON EXTRAS	
FLOORING	CHIP ON PLANK INFRONT OF SINK	

Enrollment:

Purchaser Name: Amit Kumari

Ojasvi Kumari

Phone Res:

Phone Bus: (647) 991-8652

Closing Date: September 22, 2022
Inspector: Gisella Fiore

ZANCOR HOMES PDI

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 112A / 1

Plan:

Address: Municiaplity:

Inspection Date: September 20, 2022

LIVING ROOM		
WALLS	SECURE FIREPLACE AT WALL GAPS ON ALL SIDES	
POWDER ROOM		
NOTE:	CHIP ON LOWER RIGHT CABINET BELOW SINK	
BASEMENT		
NOTE:	CHIPS ON 3RD TREAD AT STAIRS FROM LANDING TO MAIN FLOOR 2) CHIP AT INSIDE STRINGER	
	BY 3RD TREAD TO MAIN FLOOR	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the

designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Amit Kumari Ojasvi Kumari

Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature

Gisella Fiore

Designate's Name (print) Designatere Inspector's Name (print) Inspector's Signature

Date (YYYY/MM/DD) 2022/09/20 September 20, 2022