



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W166376  
Pack Slip:209295

Service Date: Oct 05, 2022

Priority: Normal Status: SCHEDULED

**BUILDER**

Customer: N000508 City: WHITBY Received: Aug 29, 2022  
Name: ZANCOR WHITBY Service Phone(s):  
Service Fax: Site Phone: Order: D374351-1  
Site Fax: Lot#: BLK 9 - 53 Phase: PH1

**RESIDENT INFORMATION**

Home Owner Name: Address:  
Home Phone(s): Work Phone(s):  
Cell Phone(s): Email(s):

**LINKED ORDER INFORMATION (D374351-1)**

Customer: N000508 ZANCOR WHITBY Lot #: BLK 9 - 53  
Model: RLT-01 Phase: PH1

**SERVICE INSTRUCTIONS**

FRONT GROUND FLOOR DOOR FOR OUR HOMEOWNER SHE FINDS THE DOOR VERY HARD TO BE ABLE TO UNLATCH DURING OPENING THE DOOR!

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

MANNY



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W166376  
Pack Slip: 209295  
Service Date: Sep 21, 2022

Priority: Normal

Status: SCHEDULED

**BUILDER**

Customer: N000508  
Name: ZANCOR WHITBY  
Service Fax:  
Site Fax:

City: WHITBY  
Service Phone(s):  
Site Phone:  
Lot#: BLK 9 - 53

Received: Aug 29, 2022  
Time:  
Order: D374351-1  
Phase: PH1

**RESIDENT INFORMATION**

Home Owner Name:  
Home Phone(s):  
Cell Phone(s):

Address:  
Work Phone(s):  
Email(s):

**LINKED ORDER INFORMATION (D374351-1)**

Customer: N000508 ZANCOR WHITBY  
Model: RLT-01

Lot #: BLK 9 - 53  
Phase: PH1

**SERVICE INSTRUCTIONS**

FRONT GROUND FLOOR DOOR FOR OUR HOMEOWNER SHE FINDS THE DOOR VERY HARD TO BE ABLE TO UNLATCH DURING OPENING THE DOOR!

Problem Description:

*Reschedule - no time*

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed: *Sept 21/22*

Approved:

Time:

Service Signature: *[Signature]*

STEVE



**Zancor Homes (Parkview) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date:** 11Aug22

**Address:**

**Location:** Now Towns In Brooklin - Phase: 1 - Lot: Unit 53 (Block 9)

**Today's Date:** 26Jul22

**Contact(s):**

**Email:**

**Company:** Newmar

**Attention:** Alex

**Telephone:** (905) 672-1233

**Fax:** (905) 672-6350


**Please Complete the following items:**

DAI	Type	Issue		Appt. Date/Time	Notes
149054	PDI	DINING ROOM- WINDOWS~TRIM BELOW BALCONY DOORS AT FRONT OF HOUSE CHIIPPED			
149065	PDI	FOYER/HALL- FRONT DOORS~ADJUST FRONT DOOR CANNOT OPEN			

**Date Completed:**

Oct 5, 2022

**Homeowner Signature:**



The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

**Date Completed:**

\_\_\_\_\_

**Trade &/or Service Tech.**

**Signature:**

\_\_\_\_\_

**Print Name:**


\_\_\_\_\_

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and its group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

**Now Towns In Brooklin - Phase: 1 - Lot: Unit 53 (Block 9)**

**149054 - 1 - WINDOWS~TRIM BELOW BALCONY  
DOORS AT FRONT OF HOUSE CHIIPPED**



**149065 - 1 - FRONT DOORS~ADJUST FRONT  
DOOR CANNOT OPEN**

