



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W161454  
Pack Slip:169983

Service Date: Oct 07, 2022

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 610908 City: KING CITY Received: Jun 08, 2022  
Name: ZANCOR MARKET COLLECTION Service Phone(s): Time: 1ST CALL  
Service Fax: Site Phone: Order: D365187-1  
Site Fax: Lot#: BLK 1-1 Phase:

RESIDENT INFORMATION

Home Owner Name: Address: 68 TATTON COURT, KING CITY, ONTARIO  
Home Phone(s): Work Phone(s):  
Cell Phone(s): 416-720-0853 Email(s): sheila.zaretsky@gmail.com

LINKED ORDER INFORMATION (D365187-1)

Customer: 610908 ZANCOR THE VILLAGE AT KINGS RIDGE Lot #: BLK 1-1  
Model: TH-02 COR Phase:

SERVICE INSTRUCTIONS

LIVING ROOM- GENERAL- #1- TOP PANEL OF WINDOW IS CRACKED- INSPECT STRESS CRACK  
GENERAL- #2- VARIOUS- WINDOWS DO NOT CLOSE PROPERLY

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
32	NEWMAR VINYL PICTURE WINDOW	GRT	GLASS ONLY - FIXED	21.875 X 15.875	AG22 DW/WH LOWE_ARG DW	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$ 98

Labour \$ 180

P.O.#:

Cause:

Solution:

Date Completed: Oct 7/2022

Approved:

Time: 9:10 to 9:25

Service Signature: ALEX



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

FIU  
WO # W161454  
Pack Slip:169983  
Service Date: Aug 30, 2022

Priority: Normal Status: SCHEDULED RELEASED  
BUILDER  
Customer: 610908 City: KING CITY Received: Jun 08, 2022  
Name: ZANCOR MARKET COLLECTION Service Phone(s): Time: 1ST CALL  
Service Fax: Site Phone: Order: D365187-1  
Site Fax: Lot#: BLK 1-1 Phase:

RESIDENT INFORMATION

Home Owner Name: Address: 68 TATTON COURT, KING CITY, ONTARIO  
Home Phone(s): Work Phone(s):  
Cell Phone(s): 416-720-0853 Email(s): sheila.zaretsky@gmail.com

LINKED ORDER INFORMATION (D365187-1)

Customer: 610908 ZANCOR THE VILLAGE AT KINGS RIDGE Lot #: BLK 1-1  
Model: TH-02 COR Phase:

SERVICE INSTRUCTIONS

LIVING ROOM- GENERAL- #1- TOP PANEL OF WINDOW IS CRACKED- INSPECT STRESS CRACK  
GENERAL- #2- VARIOUS- WINDOWS DO NOT CLOSE PROPERLY

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
32	NEWMAR VINYL PICTURE WINDOW	GRT	GLASS ONLY - FIXED	21.875 X 15.875	AG22 DW/WH LOWE_ARG DW	1

Problem Description:

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$

Labour \$

Labour \$

P.O.#:

Cause: NOT HOME

Solution:

Date Completed: 8-30-2022

Approved:

Time:

Service Signature: JULIO



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1970

WO # W161454  
Pack Slip: 169983

Service Date: Jun 20, 2022

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 610908  
Name: ZANCOR MARKET COLLECTION  
Service Fax:  
Site Fax:

City: KING CITY  
Service Phone(s):  
Site Phone:  
Lot#: BLK 1-1

Received: Jun 08, 2022  
Time: PM  
Order: D365187-1  
Phase:

RESIDENT INFORMATION

Home Owner Name:  
Home Phone(s):  
Cell Phone(s): 416-720-0853  
Address: 68 TATTON COURT, KING CITY, ONTARIO  
Work Phone(s):  
Email(s): sheila.zaretsky@gmail.com

LINKED ORDER INFORMATION (D365187-1)

Customer: 610908 ZANCOR THE VILLAGE AT KINGS RIDGE  
Model: TH-02 COR

Lot #: BLK 1-1  
Phase:

SERVICE INSTRUCTIONS

LIVING ROOM- GENERAL- #1- TOP PANEL OF WINDOW IS CRACKED- INSPECT STRESS CRACK  
GENERAL- #2- VARIOUS- WINDOWS DO NOT CLOSE PROPERLY

Problem Description:

Window glass cracked  
order to glass

21 3/4 x 15 3/4

☒ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

griffed 2/2  
Driftwood

Cause:

Solution:

Date Completed: June 20 22

Approved:

Time:

Service Signature:

THARMA



Zancor Homes (Block 81) Ltd.  
Warranty Services  
Phone: (905) 738-7010  
Fax: (905) 738-5948

## Work Order

**Closing Date:** 02Jun21  
**Address:** 68 Tatton Court  
King City, Ontario  
**Location:** The Village at Kings Ridge - Phase: 1 - Lot: Block 1 Unit 1  
**Today's Date:** 08Jun22  
**Contact(s):** Sheila Zaretsky - Cell: (416) 720-0853 - (sheila.zaretsky@gmail.com)  
**Email:** sheila.zaretsky@gmail.com

**Company:** Newmar  
**Attention:** Alex  
**Telephone:** (905) 672-1233  
**Fax:** (905) 672-6350

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
147989	1 Year	Living Room- General- #1- Top panel of window is cracked- Inspect stress crack			
147990	1 Year	Other- General- #2- various- windows do not close properly			

Date Completed: \_\_\_\_\_

Homeowner Signature: \_\_\_\_\_  
The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

Date Completed: 06/07/2022

Trade &/or Service Tech. \_\_\_\_\_

Signature: \_\_\_\_\_

Print Name: \_\_\_\_\_


Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be**

applied to the Company listed above.

**The Village at Kings Ridge - Phase: 1 - Lot: Block 1 Unit 1**

**147989 - 1 - 1 - #1- Top panel of window is cracked-  
Inspect stress crack**



**147989 - 2 - 2 - #1- Top panel of window is cracked-  
Inspect stress crack**

