



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W161860
Pack Slip:193598

Service Date: Oct 11, 2022

Priority: Normal Status: SCHEDULED

BUILDER

Customer: N000508 City: WHITBY Received: Jun 15, 2022
Name: ZANCOR WHITBY Service Phone(s): Time: AM
Service Fax: Site Phone: Order: D374427-1
Site Fax: Lot#: BLK 2 -10 Phase: PH1

RESIDENT INFORMATION

Home Owner Name: DELIA ANDREA SINCLAIR Address: 6713 THICKSON ROAD NORTH
Home Phone(s): -707-803-4172 Work Phone(s):
Cell Phone(s): 647-862-2484 Email(s): praise8383@msn.com

LINKED ORDER INFORMATION (D374427-1)

Customer: N000508 ZANCOR WHITBY Lot #: BLK 2 -10
Model: RLT-02/STC (BLK 2 UNIT 10,14) Phase: PH1

SERVICE INSTRUCTIONS

EXTERIOR- DECK-CRACK ON RIGHT FIXED BALCONY DOOR MULIN--PLEASE MR

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
40	BUCKINGHAM PURCH. PATIO DOOR po 78194	BKF	FIXED SASH AND GLASS (PH TECH AND BASE)	X X	LEFT BK CLR	1

Problem Description: *done*

☐ Warranty ☐ CHARGEABLES
Material \$ _____ Material \$ *1034*
Labour \$ _____ Labour \$ *120*
P.O.#: _____

Cause: *RePlac Fixed side Panel done*
Solution: _____

Date Completed: *OCT 11- 2022* Approved: *X [Signature]*

Time: _____ Service Signature: *[Signature]*
ZAHER
EOL



NEWMAR WINDOW MFG. INC.
ALPHA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W161860
Pack Slip: 193598

Service Date: Jul 13, 2022

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: N000508
Name: ZANCOR WHITBY
Service Fax:
Site Fax:

City: WHITBY
Service Phone(s):
Site Phone:
Lot#: BLK 2 -10

Received: Jun 15, 2022
Time:
Order: D374427-1
Phase: PH1

RESIDENT INFORMATION

Home Owner Name: Delia Sinclair, Camille
Home Phone(s): (905) 803-4172 / 647 862-2484
Cell Phone(s):

Address: 10-6713 Thickson Rd North
Work Phone(s):
Email(s): prairie8383@msn.com

LINKED ORDER INFORMATION (D374427-1)

Customer: N000508 ZANCOR WHITBY
Model: RLT-02/STC (BLK 2 UNIT 10,14)

Lot #: BLK 2 -10
Phase: PH1

SERVICE INSTRUCTIONS

EXTERIOR- DECK-CRACK ON RIGHT FIXED BALCONY DOOR MULIN--PLEASE MR

MIR

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Need Fixed Sash + Glass for 8' High 6' Wide
Survivor patio door, HL
2 man Black

Date Completed:

July 13/22

Approved:

Time:

1.5 hr

Service Signature:

STEVE