



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP
7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W157773
Pack Slip:197734
Service Date: Aug 24, 2022

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: N000508

Name: ZANCOR WHITEBY

Service Fax:

Site Fax:

City: WHITBY

Service Phone(s):

Site Phone:

Lot#: BLK 5 - 33

Received: Apr 19, 2022

Time:

Order: D374331-1

Phase: PH1

RESIDENT INFORMATION

Home Owner Name:

Home Phone(s):

Cell Phone(s): 416-668-0522

Address:

Work Phone(s):

Email(s): ryan@nwm.ca, alana.iaboni@gmail.com

LINKED ORDER INFORMATION (D374331-1)

Customer: N000508 ZANCOR WHITEBY

Model: TH-3 / INT END

Lot #: BLK 5 - 33

Phase: PH1

SERVICE INSTRUCTIONS

HI ALL: ORDER 374331-3
THIS WINDOW WAS COMPLETED LAST NIGHT, AND IT'S AT THE BACK IN THE PICKING AREA. NOTE LINES 222 AND 223 WERE DONE WITH PLYWOOD , I AM NOT SURE IF THE TEMP. GLASS WAS ORDERED YET FOR SERVICE TO INSTALL THE GLASS ON SITE.

PO #76699 ETA 04-25-2022
DINING ROOM- WINDOWS-SCRATCH ON BALCONY SLIDING DOOR CHIPPED TO DO

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
222	NEWMAR VINYL CASEMENT FIXED PO #76699 ETA 04-25-2022 COMPLETED	ADD/RR/RE C	GLASS ONLY - FIXED	18.75 X 12.75	CLR 4T/11/4T LOWE_ARG BK	1
223	NEWMAR VINYL CASEMENT FIXED PO #76699 ETA 04-25-2022 DINING ROOM- WINDOWS-SCRA COMPLETED	ADD/RR/RE C	GLASS ONLY - FIXED	48.75 X 12.75	CLR 4T/11/4T LOWE_ARG BK	1
320	BUCKINGHAM PURCH. PATIO DOOR REC po 78180	PATIO DOOR REC	OTHER RPLCMNT PARTS	71.5 X 95.5	BK 61316 LEFT BUCKINGHAM PURCH. PATIO DOOR	1
330	BUCKINGHAM PURCH. PATIO DOOR BKF po 78061	PATIO DOOR BKF	SASH AND GLASS	X	RIGHT BK CLR LOWE_ARG	1

Problem Description: Patio door or panel don't needed

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$ 1246.1170

Labour \$

Labour \$ 1000.0000

P.O.#:

Cause: Fixed The scratched out the patio door panel

Solution: done

Date Completed: Aug 24-2022

Approved: 

Time: _____

Service Signature:  ZAHIER 



NEWMAR WINDOW MFG. INC.
ALPHA LUMBER GROUP
7030 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W157773
Pack Slip:197734
Service Date: May 13, 2022

Priority: Normal
Status: SCHEDULED
RELEASED
BUILDER
Customer: N000508
City: WHITBY
Received: Apr 19, 2022
Name: ZANCOR WHITBY
Service Phone(s):
Time:
Service Fax:
Site Phone:
Order: D374331-1
Site Fax: Lot#: BLK 5 - 33
Phase: PH1

RESIDENT INFORMATION

Home Owner Name:
Address:
Home Phone(s):
Work Phone(s):
Cell Phone(s):
Email(s):

LINKED ORDER INFORMATION (D374331-1)

Customer: N000508 ZANCOR WHITBY
Lot #: BLK 5 - 33
Model: TH-3 / INT END
Phase: PH1

SERVICE INSTRUCTIONS

HI ALL; ORDER 374331-3

THIS WINDOW WAS COMPLETED LAST NIGHT, AND IT'S AT THE BACK IN THE PICKING AREA. NOTE LINES 222 AND 223 WERE DONE WITH PLYWOOD, I AM NOT SURE IF THE TEMP. GLASS WAS ORDERED YET FOR SERVICE TO INSTALL THE GLASS ON SITE.

PO #76699 ETA 04-25-2022
DINING ROOM- WINDOWS-SCRATCH ON BALCONY SLIDING DOOR CHIPPED

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
222	NEWMAR VINYL CASEMENT FIXED PO #76699 ETA 04-25-2022	ADD/RR/RE C	GLASS ONLY - FIXED	18.75 X 12.75	CLR 4T/1/4T LOWE_ARG BK	1
223	NEWMAR VINYL CASEMENT FIXED PO #76699 ETA 04-25-2022 DINING ROOM- WINDOWS-SCRA	ADD/RR/RE C	GLASS ONLY - FIXED	48.75 X 12.75	CLR 4T/1/4T LOWE_ARG BK	1

Problem Description:

☐ Warranty

Material \$

Labour \$

Cause:

Solution:

Date Completed: May 13/22

Approved:

Time: 3:00pm

Service Signature:

STEVE