



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP
7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W167695
Pack Slip:209294
Service Date: Oct 05, 2022

Priority: Normal Status: SCHEDULED

BUILDER

Customer: N000508 City: WHITBY Received: Sep 19, 2022

Name: ZANCOR WHITBY Service Phone(s): Time:

Service Fax: Site Phone: Order: D374350-1

Site Fax: Lot#: BLK 9 - 52 Phase: PH1

RESIDENT INFORMATION

Home Owner Name:

Home Phone(s): Address:

Cell Phone(s): Work Phone(s):

Email(s):

LINKED ORDER INFORMATION (D374350-1)

Customer: N000508 ZANCOR WHITBY Lot #: BLK 9 - 52

Model: RLT-03 Phase: PH1

SERVICE INSTRUCTIONS

LIVING ROOM- WINDOWS-WINDOW SCREEN NOT INSTALLED LEFT OF BALCONY DOOR

Comp

(PLEASE ASK SITE FOR KEY - NATHAN)

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
85	NEWMAR VINYL CASEMENT	REC/LIV	SCREENS-REPLA	19.0625 X		2
			CEMENT-WINDO	57.125		
			WS			

Problem Description:

☐ Warranty

Material \$

Labour \$

Cause:

☐ CHARGEABLES

Material \$

Labour \$

P.O.#

Solution:

Oct 5, 2002

Date Completed:

Approved:

MANNY

Time:

Service Signature: