



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W168266
Pack Slip: 215752

Service Date: Oct 21, 2022

Priority: Normal Status: SCHEDULED

BUILDER

Customer: N000508 City: WHITBY Received: Sep 26, 2022
Name: ZANCOR WHITBY Service Phone(s): Time:
Service Fax: Site Phone: Order: D374337-1
Site Fax: Lot#: BLK 7 - 39 Phase: PH1

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D374337-1)

Customer: N000508 ZANCOR WHITBY Lot #: BLK 7 - 39
Model: TH-3 / CORNER Phase: PH1

SERVICE INSTRUCTIONS

PATIO DOOR SASH NEED TO BE REPLACED
PO#77884

NICHOLAS IS ON-SITE AND WILL GIVE ACCESS

Complete

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
110	BUCKINGHAM PURCH. PATIO DOOR PO#77884	REC	SASH AND GLASS	X	RIGHT BK CLR LOWE_ARG	1
COMPLETED						
220	BUCKINGHAM PURCH. PATIO DOOR sash wheelies	REC	OTHER RPLCMNT PARTS	71.5 X 95.5	BK 61316 RIGHT BUCKINGHAM PURCH. PATIO DOOR	1

Problem Description: 1377 Lock Box Code nobody on site to sign

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$ 53
note 120

Labour \$

Labour \$
P.O.#: n/c

Cause: Front Living Room - need 1 18 3/4 x 56 3/4 AG 13 Bk Bottom Air Fall

Solution: Also cleaned all patio door sashes, Adjusted Master Bed patio screen, touch-up front door paint

Date Completed: Oct 21/22

Approved:

Time: 12:00

Service Signature: STEVE