Enrollment:

Purchaser Name: Nima, Mir Alamshahi

Abdul Sayed Mohd Alamshahi

Phone Res:

Phone Bus: (416) 710-9073

Closing Date: March 17, 2022 Inspector: Gisella Fiore ZANCOR HOMES PDI Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 30W / 3

Plan: Address:

Municiaplity:
Inspection Date: November 09, 2022

Muni
Page 1 of 2 Inspection

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH		
COUNTERTOPS	CHIP AT SIDE SPLASH RIGHT OF SINK	
VANITY CABINETS	CHIP AT LOWER GABLE BELOW LEFT SINK	
MAIN BATHROOM		
COUNTERTOPS	CHIP ON SIDE SPLASH	
KITCHEN		
CABINETS	CHIP INSIDE UPPER RIGHT CABINET RIGHT OF HOOD FAN 2) CHIP ON LOWER GABLE RIGHT OF HOOD FAN 3) CHIP INSIDE BOTTOM GABLE RIGHT OF BANK OF DRAWERS AND AT SHELF 4)	
	CHIP AT BOTTOM LEFT CABINET AT BOTH LEFT DOORS RIGHT OF FRIDGE 5) DENT ON UPPER RIGHT CABINET RIGHT OF FRIDGE 6) CHIP ON BOTTOM LEFT CABINET BELOW SINK	
EXTERIOR		
NOTE:	SCRATCH ON LEFT FIXED WINDOW IN DINNING AREA	
	SPRAY FOAM REQUIRED BELOW SIDE ENTRANCE DOOR	
	CAULKING REQUIRED AT GAS LINE AND AT REAR	
	MISSING VENT LEFT OF AC	
	CAULKING REQUIRED AT EXTERIOR HOSE	
	BLACK TARP RIPPED LEFT SIDE OF HOUSE	
	COLD CELLAR VENT MISSING OUTSIDE	
PORCH	GAP BETWEEN BRINK AND CEILING AND COLUMNS AND CEILING 2) GAP BETWEEN HARDY BOARD AT FRONT PORCH	
BRICKS	MISSING MOTAR BELOW LEFT WINDOW FRONT PORCH	
	GAP LEFT OF EAVESTROUGH LEFT OF GARAGE DOOR	
	CHIPPED BRICK LEFT OF SLIDING DOOR	
GARAGE DOORS	GARAGE TRIM DAMAGED LEFT AND RIGHT SIDE	
LAUNDRY ROOM		
NOTE:	MISSING SCREWS ON DRYER OUTLET	
FOYER/HALL		
STAIRS	VARNISH REQUIRED AT TRIM BELOW NOISING AT STAIRS FROM MUDROOM	

Enrollment:

Purchaser Name: Nima, Mir Alamshahi

Abdul Sayed Mohd Alamshahi

DENT ON MAN DOOR FROM GARAGE

2022/11/09

Phone Res:

FOYER/HALL

Date (YYYY/MM/DD)

WINDOWS BASEMENT

Phone Bus: (416) 710-9073
Closing Date: March 17, 2022
Inspector: Gisella Fiore



Page 2 of 2

Vendor / Builder: 44528

Project: Zancor Homes (Innisfil) Ltd.

Lot / Phase: 30W / 3 Plan:

Address: Municiaplity:

Inspection Date: November 09, 2022

NOTE: E	UCTS NOT CLEANED					
THE COMPLETED PRE-DELIVERY A REFERENCE FOR FUTURE WAR		HOME'S CONDITION BEFORE THE PURCHASEF	R TAKES POSSESSION IT WILL BE USED AS			
* Purchasers or owners who intend	to designate someone to conduct the PDI in the	eir place should ensure they provide written author	ity to the vendor/builder authorizing the			
designate to sign this form on their						
I have inspected my new home and I agree that the description of the items listed on this form are accurate.						
	510					
Nima, Mir Alamshahi	Elen	Abdul Sayed Mohd Alamshahi				
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature			
			Lh 1			
		Gisella Fiore				
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature			

November 09, 2022