

139

Nov 10

Kitchen Q.C.

JATIN

KEY
AccessKitchen

- Upper right of window: Top shelf chipped
- Ceiling of cabinet chipped
- Left side chipped
- Corner upper 2nd shelf rough right edge
- Upper right of stove: Scratch on back panel
- Upper left of stove: Floor chipped
- Floor rough left edge
- Laminated slip fallen over @ corner
- Edge upper: Shelf chipped
- Rough inside edge
- Large chips in O/W enclosure
- Lower @ sink: cabinet chipped
- Corner piece chipped
- Drawers right of stove: Bottom missing bumper
- Drawers left of stove: Right side chipped
- Island shelves: Rough edges

Master Ensuite

- Red residue on counter
- Floor chipped

Main BathLaundry

- Cut out sink → ASK MARY FOR TEMPLATE
- chips on inside of right panel by kick

MARY
416 791 1219

159