Enrollment:

Purchaser Name: Marina Rogachevsky

Phone Res:

Phone Bus: (416) 878-8141

HOMES

Vendor / Builder:

Project: Zancor Homes (Wasaga) Ltd.

Lot / Phase: 143 / 1 Plan:

Address: Municiaplity:

Inspection Date: November 16, 2022

Closing Date: November 17, 2022 Inspector: Gisella Fiore

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH		
SHOWER ENCLOSURE	SHOWER GLASS NOT INSTALLED AND MIRRORS THROUGHOUT NOT INSTALLED	
TUB	TUB NOT INSTALLED	
FOYER/HALL		
STAIRS	MISSING SCREWS AT PICKETS BELOW RAILING AT RAILING TO 2ND FLOOR	
	CHIP ON 3RD TREAD AT STAIRS FROM FOYER TO MAIN MAIN FLOOR	
	HOMEOWNER REQUESTING VARNISH AT EDGES OF PICKETS BY 4RTH AND 5TH TREAD AT STAIRS FROM MAIN FLOOR TO 2ND FLOOR	
FLOORING	CHIP ON 2ND HARDWOOD PLANK FROM L,EFT WALL AT FIRST LANDING AT STAIRS FROM MAIN FLOOR TO SECOND	
LAUNDRY ROOM		
CABINETS	ADJUST RIGHT DRAWER BELOW SINK	
BASEMENT		
NOTE:	DRYWALL NOT PAINTED	
	INSPECT WATER AT MAIN DRAIN LEFT OF STAIRS	
EXTERIOR		
NOTE:	SIDING AT FRONT PORCH NOT COMPLETE	
	DOWNSPOUT AND EAVES NOT INSTALLED	
	COLUMNS AT FRONT PORCH NOT COMPLETE	
	CAULKING NOT COMPLETE AT EXTERIOR	
BRICKS	BRICK NOT COMPLETE AT FRONT OF HOME	
GARAGE DOORS	GARAGE DOORS NOT INSTALLED	
PAINT	PAINTING NOT COMPLETE THROUGHOUT	

Enrollment:

Purchaser Name: Marina Rogachevsky

Phone Res:

Phone Bus: (416) 878-8141



Vendor / Builder:

Project: Zancor Homes (Wasaga) Ltd.

Lot / Phase: 143 / 1

Plan:

Address: Municiaplity:

Inspection Date: November 16, 2022

osing Date:	November 17, 2022	
Inspector:	Gisella Fiore	Page 2 of 2

A REFERENCE FOR FUTURE WARF	NANTY REQUESTS. In designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHASE neir place should ensure they provide written auth					
I have inspected my new home and I agree that the description of the items listed on this form are accurate.							
	- 1						
Marina Rogachevsky							
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature				
			Ihl.				
		Gisella Fiore					
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature				
Data (VVVV/MM/DD)	2022/11/16	Nevember 16, 2022					