



Service Completion Status Report

Zancor

Date : Nov 29, 2022

Fax :

Phone :

ZAN10 — ZANCOR-670-672 WINONA DR.11-19

Report To: N/A

Lot Number	Work Description	Status Status Date	Builder Ref #
670	FACE/EXTERIOR BRICK MORTAR HAS DISAPPEARED ABOVE THE MAIN WEST WINDOW <i>** Duplicate Item previously received on 10/14/2021. Builder Ref #: 146088. MG Service #: S-062650. **</i>	Completed 11/29/2022	146088 S-066410
670	BRICK MORTAR HAS DISAPPEARED ABOVE THE MAIN WINDOW ON THE WEST WALL (NORTH MOST CORNER AS WELL AS DIRECTLY ON TOP) AS WELL AS SOME OTHER AREAS. THIS WAS REPORTED ON 1 YEAR FORM AND IS STILL OUTSTANDING <i>** Duplicate Item previously received on 10/14/2021. Builder Ref #: 146088. MG Service #: S-062650. **</i>	Completed 11/29/2022	151248 S-066410