



Parkview Holdings Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date:

Address: 670 Winona Dr

Location: 670 Winona Dr - Phase: 1 - Lot: 670 Winona Dr

Today's Date: 14Oct21

Contact(s): Steve -

Email:

Company: Medi Group

Attention:

Telephone: (416) 741-2737

Fax: (416) 741-1593

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
146083	1 Year	Exterior- General- Item #64- porch- brick below front door has mortar all over from PDI		27Oct21 /am	
146088	1 Year	Exterior- General- Item #69-building face/exterior brick mortar has disappeared above the main west window		27Oct21 /am	Completed Nov. 28/

Date Completed: _____

Homeowner Signature: _____

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: Nov. 29/22

Trade &/or Service Tech.

Signature: 

Print Name: Teresa Mani

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form



MEDI GROUP Service

WO Number : **W-084971**WO Date : **24-Nov-2022**Issued To : **MICHAEL KLOC**

Builder : Zancor

ZAN10

Lot No : 670

Project : ZANCOR-670-672 WINONA DR.11-19

Model : Lot 670

Directions : 670 and 672 Winona Ave., Toronto
West of Allen, south of Eglinton

Address :

Contact :

Main Brick : Tuxedo Max

Main Stone :

Accent Brick :

Accent Stone :

INIT	Item	Work Description	PO	Builder Ref #
	1	BUILDING FACE/ EXTERIOR BRICK MORTAR HAS DISAPPEARED ABOVE THE MAIN WEST WINDOW		670OCT1421
				S-062650

BACKSIDE 670

TUCKPOINTING BACK AND FRONT 672

⑦

Homeowner Signature

Date Completed

Site Super Signature

Date Completed

Special Notes :

COMPLETED NOV 29 2022