## **Work Order**



Parkview Holdings Ltd. **Warranty Services** Phone: (905) 738-7010

Fax: (905) 738-5948

Closi	

Address:

670 Winona Dr

Location:

670 Winona Dr - Phase: 1 - Lot: 670 Winona Dr

Today's Date:

27Oct21

Contact(s):

Steve -

Email:

Company: Medi Group

Attention:

Telephone:

(416) 741-2737

Fax:

(416) 741-1593

Please Complete the following items:

DAI	Туре	Issue	Appt. Date/Time	Notes
146075	1 Year	Exterior- General- Item #56- window sills need cleaning	27Oct21 /am	
146083	1 Year	Exterior- General- Item #64- porch- brick below front door has mortar all over from PDI	27Oct21 /am	
146088	1 Year	Exterior- General- Item #69-building face/exterior brick mortar has disappeared above the main west window	27Oct21 /am	

Date Completed:	Homeowner Signature:
	The Homeowner acknowledges and accepts all work has been completed in a workman like manner.
Date Completed: 09/09/2022	Trade &/or Service Tech.
	Signature:
	Print Name: Medi Group Inc

## **MEDI GROUP Service**

WO Number:

W-083192

WO Date : 02-Sep-2022

MEDI GROUP Issued To : GTA TARPING

**Builder: Zancor** 

**ZAN10** 

Lot No: 670

Project: ZANCOR-670-672 WINONA DR.11-19

Model: Lot 670

Directions: 670 and 672 Winona Ave., Toronto

West of Allen, south of Eglinton

Address:

Contact:

Main Brick: Tuxedo Max

Main Stone:

Accent Brick:

**Accent Stone:** 

INIT

**Item Work Description** 

PO **Builder Ref #** 

WINDOW SILLS NEED CLEANING. note: You may need to

10M100358

contact this homeowner for access.

S-062817

stevenwalt@gmail.com or 647-973-9258

BRICK BELOW FRONT DOOR HAS BEEN MORTAR ALL **ÓVER.** note: You may need to contact this homeowner for access.

10M100358

S-062817

stevenwalt@gmail.com or 647-973-9258

Homeowner Signature

Special Notes:

COMPLETED SEP 0 9 2022

Site Super Signature

**Date Completed**