



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W172938
Pack Slip:217230

Service Date: Dec 01, 2022

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 611313 City: INNISFIL Received: Nov 23, 2022
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D380366-1
Site Fax: Lot#: 37W Phase: 3

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D380366-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 37W
Model: 42-06 MASTHEAD/OP 2FL(WH) Phase: 3

SERVICE INSTRUCTIONS

THE GARAGE MAN DOOR JAMB NEEDS TO BE REPAIRED

** THIS IS A MUST DO PLEASE **

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
200	2' 8" WOOD DOOR SYS door jamb needs to be repaired	G/H	OTHER RPLCMNT PARTS	33.75 X 81.75	61316 FJ LEFT 2' 8" WOOD DOOR SYS	1

Problem Description: _____

☐ Warranty

Material \$ _____

Labour \$ _____

☐ CHARGEABLES

Material \$ NIC

Labour \$ _____

P.O.#: _____

Cause: _____

Solution: Nothing wrong with any of the doors

Date Completed: _____

Approved: _____

Time: _____

Service Signature: _____

PHIL

11/23/22, 2:34 PM

Newmar / Casa Bella Mail - Lot 37w



Service Department <servicedept@newmar.com>

Lot 37w

1 message

Nathan Simas <nathan@zancorhomes.com>
To: Service Department <servicedept@newmar.com>

Tue, Nov 22, 2022 at 12:04 PM

Good morning

The garage man door jamb needs to be repaired

Thanks,

Nathan Simas
Finishing Supervisor
Now Towns in Brooklin / Belle Aire Shores
Cell # 416-791-9862
nathan@zancorhomes.com