

## **Service Completion Status Report**

**Date**: Dec 6, 2022

Fax: Phone :

Zancor

Lot Number	Work Description	Status Status Date	Builder Ref#
9	INCOMPLETE MORTAR WORK ABOVE WINDOWS OVER TOP OF GARAGE NOTE: CHERRY PICKER NEEDED	<b>Completed</b> 12/06/2022	<b>9JUL262</b> S-06539

Page 1 of 1 December 06, 2022 12:46 Grace M