

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W167829 Pack Slip:209163

Service Date: Jan 02, 2023

newinai				
Priority: Normal	Status:	SCHEDULED		RELEASED
BUILDER				
Customer: N000531	City:	CALEDON	Received:	Sep 20, 2022
Name: ZANCOR CALEDON CLUB	Service Phone(s):		Time:	
Service Fax:	Site Phone:		Order:	D380120-1
Site Fax:	Lot#:	114A	Phase:	
RESIDENT INFORMATION				
Home Owner Name: PREETPAL, SINGH BAINS	Address:			
Home Phone(s):	Work Pho	one(s): 647-877-	-3654	
Cell Phone(s):	Email(s):	preetpal.	bains123@gmail.con	n
LINKED ORDER INFORMATION (D380120-1)				
Customer: N000531 ZANCOR CALEDON CLUB		Lot #: 114	IA.	
Model: 30-04 GLENCAIRN (OPT. 4BED)(BK)		Phase:		
SERVICE INSTRUCTIONS		1	21-	
DINING ROOM- WINDOWS-CRACKED LEFT OPERA	TING GLASS	Cour	letre	
PARTS REQUIRED		0		
LN Item Description Location	Specification	Size	Options	Qty
32 NEWMAR VINYL CASEMENT FIXED RR/ G.ROOM	GLASS ONLY - FIXED	18.75 X 62.75	CLR LOWE_ARG	BK 1
Problem Description: tenent d	12 not 8:4	u		
Warranty	CHAR	GEABLES		
Material \$	Material S	108		
_abour \$	Labour \$	120		
	P.O.#:			
Cause:				
National Control of the Control of t				
Solution:				
1				
Date Completed: Jun 62 22	Appr	oved:		
Time: 40mm			//	
Time: 50mm	Service Signa	ature:		
		0	STEVE	



## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076

WO # W167829 Pack Slip:209163

Service Date: Nov 02, 2022

Priority: BUILDER	Normal		Status:	SCHEDULED		RELEASED
Customer:	N000531		City:	CALEDON	Received:	Sep 20, 2022
Name:	ZANCOR CALEDON CLUB		Service Phone(s):		Time:	
Service Fax:			Site Phone:		Order:	D380120-1
Site Fax:			Lot#:	114A	Phase:	
RESIDENT I	NFORMATION					
Home Owner	Name: PREETPAL, SINGH E	BAINS	Address:			
Home Phone(	s):		Work Ph	one(s): 647-877-	-3654	
Cell Phone(s):			Email(s):	preetpal.	bains123@gmail.com	
LINKED OR	DER INFORMATION (D380	120-1)				
Customer: 1	N000531 ZANCOR CALEDON	CLUB		Lot #: 114	1A	
Model: 3	30-04 GLENCAIRN (OPT. 4BE	D)(BK)		Phase:		
SERVICE IN	STRUCTIONS					
DINING ROOM	M- WINDOWS-CRACKED LEF	T OPERATIN	IG GLASS			
PARTS REQ						
LN Item Descr	ription	Location	Specification	Size	Options	Qty
32 NEWMAI	R VINYL CASEMENT FIXED	RR/ G.ROOM	GLASS ONLY - FIXED	18.75 X 62.75	CLR LOWE_ARG B	
Problem Desci	ription: H/o ne	of ho	me No	access	ж	
Warranty			CHAR	GEABLES		
Material \$			Material S			
Labour \$			Labour \$			
			P.O.#:			
Cause:						
Solution:						
Date Comple	eted:	7.2	Appr	oved:		
Ti	ime:		Service Signs	ature;	The	
					THARMA	



Closing Date: 19May22

ZANCOR Zancor Homes (Caledon) Ltd. Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

**Work Order** 

Address	. Iomay L					
Address: Location:	Caledor	Club - Phase: 1 - Lot; 114	44			
Today's Date			***			
Contact(s):		, Singh Bains - Work: (647)	877-3654	- (preetpal.ba	ins123@gmail.com)	
Email:	preetpal	bains123@gmail.com				
Company:	Newma				AM BUILDS - TA	
Attention:	Alex (905) 67	1 4122				
Telephone: Fax:	(905) 67					
r ax.	(903) 07	2-0330				
Please Com	lete the fell	owing items:				
			T I		In a	1
DAI	Туре	Issue		Appt.	Notes	
				Date/Time		
150056	PDI	DINING ROOM-				
	1	WINDOWS~CRACKE				
		D LEFT OPERATING				
		GLASS				
	1		1 1			J.
Date Comp	leted:		Homeov	vner Signatu	re;	
_ 2.0 001110					knowledges and accepts	all work
					in a workman like manne	
	1		,,,,,			
Date Completed: Jan 223		Trade &/or Service Tech.				
	V					
			Signatur	e: 4	- les	
			•	me: 5 Fz	1, ,	
			Print Na	me: Ste	wen Maria	

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Caledon Club - Phase: 1 - Lot: 114A

150056 - 1 - WINDOWS~CRACKED LEFT OPERATING GLASS

