



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W169540

Pack Slip:224594

Service Date: Jan 04, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Oct 14, 2022
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time: 1ST CALL
Service Fax: Site Phone: Order: D388443-1
Site Fax: Lot#: 157W Phase:

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D388443-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 157W
Model: 36-05 GALLEY OP 2FL/3BTH/DW Phase:

SERVICE INSTRUCTIONS

REPLACE FRONT DOOR SLAB- DAMAGED

Complete

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
161	5' 8" CLAD DOOR SYS 22 X 48 cutout	FOY	SLABS-OPERATIN G FOR DOUBLE DRS	70.5 X 81.75	LEFT STEEL 200_SERIES TYPE1 DW	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$ 757

Labour \$ 120

P.O.#:

Cause:

Solution:


Date Completed: Jan 4 2023

Approved: Ch

Time: 1hr

Service Signature: *[Signature]*

STEVE





NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W169540
Pack Slip: 224594
Service Date: Nov 17, 2022

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Oct 14, 2022
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D388443-1
Site Fax: Lot#: 157W Phase:

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D388443-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 157W
Model: 36-05 GALLEY OP 2FL/3BTH/DW Phase:

SERVICE INSTRUCTIONS

REPLACE FRONT DOOR SLAB- DAMAGED

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
161	5' 8" CLAD DOOR SYS 22 X 48 cutout	FOY	SLABS-OPERATIN G FOR DOUBLE DRS	70.5 X 81.75	LEFT STEEL 200_SERIES TYPE1 DW	1

Problem Description:

Fresh paint

Reschedule

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Nov 17/22

Approved:

Time:

1:50pm

Service Signature:

STEVE

10/14/22, 10:05 AM

Newmar / Casa Bella Mail - Lot 157w



Service Department <servicedept@newmar.com>

Lot 157w

1 message

Nathan Simas <nathan@zancorhomes.com>
To: Service Department <servicedept@newmar.com>

Wed, Oct 12, 2022 at 11:15 AM

Front door damaged

Thanks,

Nathan Simas
Finishing Supervisor
Now Towns in Brooklin / Belle Aire Shores
Cell # 416-791-9862
nathan@zancorhomes.com



processed-ab2bdf4b-6c4c-48e3-ad77-c5f73a13c0ae_oZ4fhhdD.jpeg
640K



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

714

WO # W169540
Pack Slip:224594

Service Date: Nov 17, 2022

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Oct 14, 2022
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D388443-1
Site Fax: Lot#: 157W Phase:

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D388443-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 157W
Model: 36-05 GALLEY OP 2FL/3BTH/DW Phase:

SERVICE INSTRUCTIONS

REPLACE FRONT DOOR SLAB- DAMAGED

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
161	5' 8" CLAD DOOR SYS 22 X 48 cutout	FOY	SLABS-OPERATIN G FOR DOUBLE DRS	70.5 X 81.75	LEFT STEEL 200__SERIES TYPE1 DW	1

Problem Description:

Fresh paint

Reschedule

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Nov 17/22

Approved:

Time:

1:00pm

Service Signature:

STEVE

10/14/22, 10:05 AM

Newmar / Casa Bella Mail - Lot 157w



Service Department <servicedept@newmar.com>

Lot 157w

1 message

Nathan Simas <nathan@zancorhomes.com>

Wed, Oct 12, 2022 at 11:15 AM

To: Service Department <servicedept@newmar.com>

Front door damaged

Thanks,


Nathan Simas

Finishing Supervisor

Now Towns in Brooklin / Belle Aire Shores

Cell # 416-791-9862

nathan@zancorhomes.com



processed-ab2bdf4b-6c4c-48e3-ad77-c5f73a13c0ae_oZ4fhhdD.jpeg
640K