



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W169693

Pack Slip:224594

Service Date: Jan 04, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Oct 17, 2022
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time: 1ST CALL
Service Fax: Site Phone: Order: D388443-1
Site Fax: Lot#: 157W Phase:

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D388443-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 157W
Model: 36-05 GALLEY OP 2FL/3BTH/DW Phase:

SERVICE INSTRUCTIONS

REAR OPERATING WINDOW MISSING
LOCK BOX ON TRAILER #1290 *Complete*

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
94	NEWMAR VINYL CASEMENT	MB	SASH AND GLASS	28.125 X 46.125	RIGHT DW CLR LOWE_ARG	1
154	NEWMAR VINYL CASEMENT	RR/GRT	SASH AND GLASS	28.125 X 54.125	RIGHT DW CLR LOWE_ARG	1

Problem Description:

☐ Warranty ☐ CHARGEABLES
Material \$ _____ Material \$ 271
Labour \$ _____ Labour \$ 120
P.O.#:

Cause:

Solution: *Replaced Sash in Great Room*

Date Completed: *Jan 04/23* Approved: *Chr*

Time: *12:00* Service Signature: *[Signature]* STEVE



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

FILE
WO # W169693
Pack Slip: 224594
Service Date: Dec 05, 2022

Priority: Normal

Status: SCHEDULED

RELEASED

BUILDER

Customer: 611313

City: INNISFIL

Received: Oct 17, 2022

Name: ZANCOR BELLE AIRE SHORES

Service Phone(s):

Time:

Service Fax:

Site Phone:

Order: D388443-1

Site Fax:

Lot#: 157W

Phase:

RESIDENT INFORMATION

Home Owner Name:

Address:

Home Phone(s):

Work Phone(s):

Cell Phone(s):

Email(s):

LINKED ORDER INFORMATION (D388443-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES

Lot #: 157W

Model: 36-05 GALLEY OP 2FL/3BTH/DW

Phase:

SERVICE INSTRUCTIONS

REAR OPERATING WINDOW MISSING

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
94	NEWMAR VINYL CASEMENT	MB	SASH AND GLASS	28.125 X 46.125	RIGHT DW CLR LOWE_ARG	1

Problem Description:

*Window size required each end glass from frame
@ 30 X 56 RH/DW for family room (1 clear glass)*

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$

Labour \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

ALEX

10/17/22, 2:22 PM

Newmar / Casa Bella Mail - Lot 157w



Service Department <servicedept@newmar.com>

Lot 157w

1 message

Nathan Simas <nathan@zancorhomes.com>

Wed, Oct 12, 2022 at 11:14 AM

To: Service Department <servicedept@newmar.com>

Rear operating window missing

Thanks,

Nathan Simas

Finishing Supervisor

Now Towns in Brooklin / Belle Aire Shores

Cell # 416-791-9862

nathan@zancorhomes.com



processed-8ec563da-a4f3-4e98-91c5-fb835059763d_Rq0bUd5u.jpeg
1225K