



Quality Sterling Group

Gerry

REPAIR ORDER
723554



NC

BUILDER: Zancor Homes

JOB SITE: Caledon Club

Customer Code:

Job Number: 18338 Board Area:8

COMPLAINT DATE: 11/30/22

LOT: 90A

INSTALLER:

SCHEDULED DATE: 12/16/22

1-4pm

OWNER NAME: KAMALJIT

OWNER TEL: 647-205-8750

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE: E-MAIL

REPAIRMAN:

BUILDER WO# 152575

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

ORIGINAL WO#: 701407

REPAIR DESC: SHIM MISSING AT ENTRANCE OF PRINCIPAL BATH

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE:

[Handwritten Signature]

SUPER'S/OWNER'S SIGNATURE:

Randeep Singh Deol

DATE: _____

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

INSTALLER SIGNATURE _____

DATE _____



Eye Protection



Foot Protection



Class A Compressed Gas



Class B Flammable and combustible material



Class C Oxidizing material



Class D Material



Class D Material



Class D Material



Class E Corrosive Material



Class F Dangerous Reactive Material

723554

Lot 90

Outstanding Deficiencies Quality Rugs Canada LTD.

Work Order Date	Lot	Phase	Site	Type DAI	Deficiency Description	Address	Contact	Appointment Date	Days Out
30Sep22	26W	3	Belle Aire Shores	PDI 150529	BEDROOM #3- NOTE:-CARPET CUT SHORT LEFT SIDE OF ROOM CAN SEE SUBS FLOOR		<u>Paolo - Home: (647) 293-4616</u> <u>L Magrone - Home: (416) 707-2778</u>	02Nov22	60
23Nov22	56A	1	Caledon Club	Interval 152542	Master Bedroom- Cut out for vent not complete		<u>Atul Kale -</u> <u>Sarika Tarachand Bhowte - Cell: (437) 770-6923</u>	NoAppoint.	6
17Nov22	57A	1	Caledon Club	PDI 152298	BEDROOM #4- FLOORING~BUBBLE IN CARPET IN CLOSEST RIGHT SIDE		<u>Abhaykumar Ramanlal Ostwal - Cell: (647) 267-9521</u> <u>Chetana Shantilal Bafana - Cell: (416) 816-6078</u>	NoAppoint.	12
17Nov22	57A	1	Caledon Club	PDI 152300	BEDROOM 2 ENSUITE- FLOORING~ADJUST CARPET SHIM AT ENTRANCE TO BATH			NoAppoint.	12
17Nov22	57A	1	Caledon Club	PDI 152306	MASTER BEDROOM- FLOORING~TUCK CARPET HUMP IN FLOOR NOT TIGHT			NoAppoint.	12
26Oct22	65A	1	Caledon Club	PDI 151432	Bedroom 4- FLOORING~REMOVE BLACK STAINS FROM CARPET- STAIN NOT COMING OUT REPLACEMENT REQUIRED		<u>Avtar - Cell: (647) 542-0035</u> <u>Singh Baring - Cell: (647) 638-7135</u>	NoAppoint.	34
24Nov22	90A	1	Caledon Club	PDI 152575	MASTER ENSUITE BATH- FLOORING~CARPET SHIM REQUIRED AT ENTRANCE TO MASTER BATH		<u>Kamaljit - Home: (289) 752-8750</u> <u>- Work: (647) 205-8750</u> <u>Singh Deol - Cell: (647) 205-8750</u>	NoAppoint.	5
14Nov22	92A	1	Caledon Club	PDI 152123	Bedroom 3- FLOORING~ADJUST CARPET SHIM AT ENTRANCED TO BATH TOO HIGH AND CARPET RAISED AT RIGHT CORNER OF WINDOW		<u>Jaspreet Singh - Cell: (647) 376-4400</u> <u>- Work: (905) 297-9272</u>	NoAppoint.	15
18Aug22	Unit 46 (Block 8)	1	Now Towns In Brooklin	30-Day 149553	Master Bedroom- item #12- floor- al the bedrooms have a gap between the middle of the carpet and hardwood at the entrance of doors		<u>Vinothan Kumaravel - Cell: (647) 991-8376</u>	02Sep22	103
23Aug22	Unit 52 (Block 9)	1	Now Towns In Brooklin	PDI 149611	MASTER BEDROOM- FLOORING~CARPET NOT INSTALLED THROUGHOUT 3RD FLOOR BED ROOM		<u>Muhammad Salman Khawaja - Cell: (647) 409-1962</u> <u>Zeb - Cell: (647) 860-7041</u>	NoAppoint.	98
08Jun22	3	1	Reserve Of Country Trails	PDI 148077	MASTER BEDROOM- FLOORING~CARPET SHIM NOT INSTALLED THROUGHOUT		<u>Kanwalrajjeet - Cell: (647) 667-1248</u>	17Aug22	174