

Outstanding Deficiencies
For AV Classic
For Caledon Club

Print Session: 756 - Printed: 18Jan23

WO Date	Lot	Phase	Site	Type	Deficiency Description	DAI	Appt. Date	Days Out	Initial
11Jul22	7A		Caledon Club	PDI	MASTER ENSUITE BATH- COUNTERTOPS~SCRATCHES ON MARBLE SURROUND AT BASE OF SHOWER	148526	05Aug22	191	
14Sep22	114A		Caledon Club	PDI	MASTER ENSUITE BATH- SHOWER ENCLOSURE~SCRATCHES ON MARBLE SURROUND AT SHOWER	150062	NoAppt.	126	
05Oct22	108A		Caledon Club	PDI	MASTER ENSUITE BATH- FLOORING~SCRATCHES ON MARBLE SURROUND	150690	01Nov22	105	
05Oct22	110A		Caledon Club	PDI	MASTER ENSUITE BATH- NOTE~MARBLE SURROUND AT TOP CRACKED LEFT OF SHOWER DOOR. BATOM CORNER SMALL CHIP	150810	16Jan23	105	
11Oct22	107A		Caledon Club	30-Day	Bedroom 2 Ensuite- General- Item #1 scratch on marble surround right side (noted on PDI)	151000	14Oct22	99	
17Nov22	116A		Caledon Club	30-Day	Kitchen- General- Item #35 grouting gaps between hardwood floor and tiled floor	152278	03Feb23	62	
17Nov22	116A		Caledon Club	30-Day	Main Bathroom- General- Item #52 dirty grouting all over the floor - Confirm correct grout colour used	152321	09Dec22	62	
18Nov22	56A		Caledon Club	Interval	Master Ensuite- General- hole is shower, grout required	152385	25Nov22	61	
21Nov22	64A		Caledon Club	Interval	Kitchen- General- tile cracked by patio door	152455	18Jan23	58	
28Nov22	108A		Caledon Club	30-Day	Througout- General- Item #8 ALL BATHROOMS have flooring issues	152615	13Dec22	51	
14Dec22	56A		Caledon Club	30-Day	Master Ensuite- General- Item #10- over cut on wall tile by the right faucet	153030	24Jan23	35	
14Dec22	56A		Caledon Club	30-Day	Kitchen- General- Item #7- kitchen tiles are not cleaned	153025	24Jan23	35	
14Dec22	62A		Caledon Club	30-Day	Main Bathroom- General- Item #85 broken tile in main washroom (shower)-EDGE	153134	18Jan23	35	
16Dec22	64A		Caledon Club	Interval	Kitchen- General- 2nd tile right of hardwood	153317	18Jan23	33	
16Dec22	83A		Caledon Club	30-Day	Kitchen- General- Item #5- grout & paint left on tiles	153322	23Jan23	33	
19Dec22	89A		Caledon Club	PDI	MAIN BATHROOM- FLOORING-REMOVE GROUT FROM SHOWER DRAIN	153401	NoAppt.	30	
20Dec22	119A		Caledon Club	PDI	MASTER ENSUITE BATH- FLOORING~ADJUST SHOWER DRAIN RAISED	153455	NoAppt.	29	
10Jan23	142A		Caledon Club	PDI	FOYER/HALL- FLOORING~OVER CUT AT TILE AT HEAT REGISTER LEFT OF FRONT DOOR	153645	NoAppt.	8	
10Jan23	142A		Caledon Club	PDI	LAUNDRY ROOM- FLOORING~TILE BASEBOARD RIGHT SIDE AT ENTRANCE TO LAUNDRY NOT FLUSH TO WALL	153627	NoAppt.	8	

Done

Done

Done

N/A

Done

N/A

Done

N/A

N/A

N/A