



Zancor Homes (Wasaga) Ltd.

Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Closing Date: 25Aug22

Address:

Location: Shoreline Point - Phase: 1 - Lot: 118

Today's Date: 07Dec22

Contact(s): Jean, Marie Ntawutarama - Cell: (416) 559-0666 - (jmntawutarama@gmail.com)

Amida Kabazayire Ntawutarama - Cell: (647) 393-7961 - (kabamida@yahoo.com)

Email: jmntawutarama@gmail.com

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
152844	PDI	Exterior- General- far right garage transom glass has stress crack		

Date Completed: Dec 15/22

Homeowner Signature: X Alex NM
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: Dec 15/22

Trade &/or Service Tech.

Signature: [Signature]

Print Name: _____

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W172641
Pack Slip: 215666
Service Date: Dec 15, 2022

Priority:	Normal	Status:	SCHEDULED	RELEASED	
BUILDER					
Customer:	N000633	City:	WASAGA BEACH	Received:	Nov 18, 2022
Name:	ZANCOR WASAGA SINGLES	Service Phone(s):		Time:	
Service Fax:		Site Phone:		Order:	D382326-1
Site Fax:		Lot#:	118	Phase:	
RESIDENT INFORMATION					
Home Owner Name:	JEAN, MARIE NTAWUTARAMA	Address:			
Home Phone(s):	416-559-0666, 647-393-7961	Work Phone(s):			
Cell Phone(s):		Email(s):	jmntawutarama@gmail.com, kabamida@yahoo.com		

LINKED ORDER INFORMATION (D382326-1)

Customer:	N000633 ZANCOR WASAGA SINGLES	Lot #:	118
Model:	40-06 (CB)	Phase:	

SERVICE INSTRUCTIONS

ADJUST FRONT DOOR (BOTTOM PIN WONT GO IN
ADD
STRESS CRACK AT GARAGE TRANSOM--OVER RIGHT DOOR, RIGHT PIECE

LN	Item Description	Location	Specification	Size	Options	Qty
141	5' 8" CLAD DOOR SYS REPLACE THE BOTTOM DOUBLE DOOR FLUSH BOLT PIN ON THE FRONT DOOR.	FOY	OTHER RPLCMNT PARTS <i>-conf</i>	72 X 97.75	CB 61316 FJ RIGHT 5' 8" CLAD DOOR SYS	1
261	NEWMAR VINYL CASEMENT FIXED	GAR	GLASS ONLY - FIXED <i>-conf</i>	44.125 X 12.75	CLR LOWE_ARG CB	2

Problem Description: _____

☐ Warranty	☐ CHARGEABLES
Material \$ _____	Material \$ <i>168</i>
Labour \$ _____	Labour \$ <i>120</i>
	P.O.#: _____

Cause: _____

Solution: _____

Date Completed: *Dec 15, 2022* Approved: _____

Time: _____ Service Signature: *KYLE*