

Zancor Homes (Caledon) Ltd.

Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Closing Date: 01Dec22

Address:

Location: Caledon Club - Phase: 1 - Lot: 90A

Today's Date: 25Nov22

Contact(s):

Email:

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
152559	PDI	LIVING ROOM- WINDOWS-SCRATC H ON RIGHT FIXED GLASS AT EXTERIOR RIGHT OF OPERATING WINDOW	Done		
152563	PDI	FOYER/HALL- FRONT DOORS-MISSING SCREW COVER BELOW HANDLE AT OPERATING DOOR	Done		Screw cover is for handle set not Doorlite (H/O to call) Builder
152564	PDI	FOYER/HALL- FRONT DOORS-DAMAGE ASTRICAL AT FRONT DOOR ABOVE HINGE	Done		
152566	PDI	FOYER/HALL- WINDOWS-SCRATC H ON LEFT FIXED GLASS LEFT OF OPERATING WINDOW AT DINNING FROM	Done		

152570	PDI	FOYER			
		BEDROOM #4- WINDOWS~DAMAGE TRIM LEFT OF OPERATING WINDOW UPPER LEFT SIDE	Done		
152571	PDI	BEDROOM #3- WINDOWS~ADJUST OPERATING WINDOW AT BEDROOM ABOVE GARAGE	Done		

Date Completed: _____

Homeowner Signature: Amarjit Kaur

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: 1/5/23


Trade &/or Service Tech.

Signature: Mike Clarke

Print Name: Mike Clarke

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 872-1233 FAX (905) 872-1076

WO # W173565
Pack Slip: 213399
Service Date: Jan 05, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000531
Name: ZANCOR CALEDON CLUB
Service Fax:
Site Fax:

City: CALEDON
Service Phone(s):
Site Phone:
Lot#: 90A
Received: Dec 02, 2022
Time:
Order: D380136-1
Phase:

RESIDENT INFORMATION

Home Owner Name: KAMALJIT SINGH DEOL
Home Phone(s): 289-752-8750
Cell Phone(s):

Address: 5 DEL GRAPPA STREET
Work Phone(s): 647-205-8750
Email(s): kamaljit.5@hotmail.com

LINKED ORDER INFORMATION (D380136-1)

Customer: N000531 ZANCOR CALEDON CLUB
Model: 38-04 GRANVIEW (SL)

Lot #: 90A
Phase:

SERVICE INSTRUCTIONS

LIVING ROOM WINDOWS- SCRATCH ON RIGHT FIXED GLASS AT EXTERIOR RIGHT OF OPERATING WINDOW - Done
FOYER/ HALL FRONT DOORS-MISSING SCREW COVER BELOW HANDLE AT OPERATING DOOR - H/o to call builder
FOYER/HALL FRONT DOORS-DAMAGE ASTRICAL AT FRONT DOOR ABOVE HINGE
FOYER/ HALL WINDOWS- SCRATCH ON LEFT FIXED GLASS LEFT OF OPERATING WINDOW AT DINNING FROM FOYER handle
BEDROOM #3- WINDOWS-ADJUST OPERATING WINDOW AT BEDROOM ABOVE GARAGE - Done

ADD

BEDROOM #4- WINDOWS-DAMAGE TRIM LEFT OF OPERATING WINDOW UPPER LEFT SIDE - Done

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty.
12	NEWMAR VINYL CASEMENT FIXED Done	RGT/ LIV/DIN	GLASS ONLY - FIXED	18.75 X 54.75	CLR LOWE_ARG SL	2
61	NEWMAR VINYL CASEMENT FIXED Done	G.ROOM	GLASS ONLY - FIXED	18.75 X 54.75	CLR LOWE_ARG SL	1
130	5' 8" CLAD DOOR SYS MISSING SCREW COVER Builder Problem	ENT	OTHER RPLCMNT PARTS	72 X 97.75	SL 61316 FJ RIGHT 5' 8" CLAD DOOR SYS	1
260	5' 8" CLAD DOOR SYS ASTRICAL DAMAGE - Done	ENT	OTHER RPLCMNT PARTS	72 X 97.75	SL 61316 FJ RIGHT 5' 8" CLAD DOOR SYS	1
428	NEWMAR VINYL CASEMENT TRIM DAMAGE	B2	OTHER RPLCMNT PARTS	24 X 68	SL 61316 FJ RIGHT EGRESS	1
520	NEWMAR VINYL CASEMENT jamb extensions - Done	LFT/ B4	OTHER RPLCMNT PARTS	24 X 48	SL 61316 FJ RIGHT	1

Problem Description:

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$ 190

Labour \$

Labour \$ 120

Cause:

P.O.#:

Solution:

Date Completed: 1/5/23

Approved:

Time:

Service Signature:



MIKE(RENO)

Bedroom #4 Damaged Sash I wood Filled easiest Fix