Outstanding Deficiencies Belle Aire Shores - Phase: 3 - Lot: 79W

| 18Jan23 PDI | 18.Jan23 PDI | 18Jan23 PDI | 18Jan23 PDI | 18.Jan23 PDI | <u>18Jan23</u> PDI | 18Jan23 PDI | <u>18Jan23</u> PDI | 18Jan23 PDI | |
|--|--|--|--|--|---|--|---|--|-------------|
| 9 | ∞ | 7 | 6 | O. | 4 | w | 2 | - | |
| MASTEK ENSUTE BATH- MIRROR-MIRROR THROUGHOUT NOT INSTALLED | MASTER BEDROOM- WALK IN CLOSET~STAIN AT CORNER OF CARPET IN MASTER | SIIARED ENSUITE- COUNTERTOPS~CHIP AT LEFT SIDE SPLASH LEFT OF SINK | BEDROOM #4- WALLS~SEAM AT CEILING LEFT OF LIGHT FIXTURE | EXTERIOR- SHINGLES~SHINGLES AT PEAK ABOVE GARAGE LEFT SIDE DAMAGED | EXTERIOR- NOTE:~CAULKING AT EXTERIOR NOT COMPLETE | FOYER/HALL-STAIRS-CHIP AT 6TH TREAD FROM MAIN FLOOR TOO IST LANDING TO 2ND FLOOR | FOYER/HALL- STAIRS~VARNISH REQUIRED AT NEWEL POST RIGHT OF STAIR AT MAIN FLOOR 2) VARNISII REQUIRED NOSING BELOW RAILING AT STAIRS TO LANDING TO BASEMENT | KITCHEN- CABINETS~CHIP AT TOP SHELVE RIGHT OF FRIDGE UPPER CABINET | |
| Metropolitan 153908 | Quality Rugs Canada LTD. 153907 | New Image Kitchens 153906 | Foremont Drywall 153905 | Trudel & Sons Roofing LTD. 153904 | CJ Caulking 153903 | Bolton Railings Inc. 153902 | Perfect Touch Painting 153901 | New Image Kitchens 153900 | Assigned |
| Add | Add | <u>Add</u> | <u>Add</u> | Add | Add | <u>Add</u> | <u>Add</u> | Add | irage |
| NoAppoint. | NoAppoint. | NoAppoint. | NoAppoint. | NoAppoint. | NoAppoint. | NoAppoint. | NoAppoint. | NoAppoint. | <u>Date</u> |
| 1 | 1 | | | | | , | 7 | 1 | Completed |
| E | 27 | | | | | | 5 | E | |

| Homeowner Signature: The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction. Date: |
|---|
| |