



Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Preot. Feb 7

Closing Date: 23Feb23

Address:

Location: Caledon Club - Phase: 1 - Lot: 147A

Today's Date: 01Feb23

Contact(s):

Email:

1234

Company: New Image Kitchens

Attention:

Telephone: (416) 739-0007

Fax: (416) 739-7031

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
154263	PDI	POWDER ROOM- NOTE:~CHIP AT BOTTOM RIGHT AND LEFT CABINET BELOW SINK		<u>Done</u>
154268	PDI	KITCHEN- CABINETS~FILL GAP AT UPPER CROWN MOULDING RIGHT SIDE		<u>Done</u>
154269	PDI	KITCHEN- CABINETS~GAP BETWEEN CABINET AT LOWER RIGHT CORNER AND UPPER RIGHT CORNER		<u>Done</u>
154270	PDI	KITCHEN- CABINETS~CRACK INSIDE UPPER RIGHT CORNER CABINET AT BACK GABLE 2) H.O REQUESTING GABLE INSIDE		<u>Done</u>

		STOVE COOKTOP RIGHT AND LEFT SIDE TO BE REPLACED WHERE GAS COOKTOP WILL BE INSERTED 3) GAP BETWEEN FILLER AND CROWN MOULDING ABOVE UPPER RIGHT GLASS CABINET 4) SCREW TO BE TURNED SO FRIDGE CAN FIT 5) CHIP AT VALANCE RIGHT OF HOOD FAN 6) SCRATCH ON BOTTOM LEFT CABINET DOOR BELOW SINK AT ISLAND			Not Possible. Cook top Exactly the same size as cab interior. DONE
154288	PDI	SHARED ENSUITE- VANITY CABINETS~CHIP AT BOTTOM RIGHT CABINET LEFT DOOR 2) H.O REQUESTING BACK GABLE BELOW BOTTOM LEFT SINK TO BE FIXED CRACKED			Done
154292	PDI	MASTER ENSUITE BATH- VANITY CABINETS~CHIP IN SIDE BOTTOM RIGHT CABINET AT BOTTOM GABLE RIGHT SIDE			Done

Date Completed: _____

Homeowner Signature: N/a

The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: 7 Feb, 2023

Trade &/or Service Tech.

Signature: Indes