

NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W162391

Pack Slip: 198441

Service Date: Feb 15, 2023

Normal

Status:

SCHEDULED

RELEASED

Order: N000508

Customer: ZANCOR WHITBY

Service Fax:

Site Fax:

City:

WHITBY

Service Phone(s):

Site Phone:

Lot#:

BLK 8 - 46

Received:

Jun 24, 2022

Time:

Order:

D374344-1

Phase:

PH1

**RESIDENT INFORMATION**

Home Owner Name: VINOTHAN KUMARAVEL

Home Phone(s):

Cell Phone(s): 647-991-8376

Address:

Work Phone(s):

Email(s): vinothan68@gmail.com

**LINKED ORDER INFORMATION (D374344-1)**

Customer: N000508 ZANCOR WHITBY

Model: TH-1

Lot #: BLK 8 - 46

Phase: PH1

**SERVICE INSTRUCTIONS**

- EXTERIOR- PORCH-SCRATCH ON LEFT MULIN AT FRONT DOOR ✓

-LIVING ROOM- WINDOWS-CRACKED OPERATING WINDOW LEFT SIDE *Comp*

-FOYER/HALL-WALLS-ADJUST FRONT DOOR ✓

-MASTER BEDROOM-WALLS-SCREEN NOT INSTALLED THROUGHOUT ✓

ADD:

LIVING ROOM- GENERAL- ITEM #8- WINDOWS- BEFORE WINDOW WAS CRACKED WHEN WE CAME HERE BUT THEY FIXED THE GLASS THEY DIDN'T CHANGE THE WINDOW PANE WHICH HAS A CRACK AND THE OPERATING HANDLE THAT IS NOT WORKING *Replaced window frame and glass comp.*

MASTER ENSUITE- GENERAL- ITEM #13- WINDOWS - THE OPERATING HANDLE IS NOT WORKING *comp*

MASTER ENSUITE- GENERAL- ITEM #14-WINDOWS- FOR THE 2 BEDROOMS THE WINDOWS DO NOT HAVE NET OPERATING HANDLE NOT WORKING *comp*

**PARTS REQUIRED**

LN	Item Description	Location	Specification	Size	Options	Qty
106	NEWMAR VINYL CASEMENT	LIV	FRAME ONLY	24 X 62	RIGHT BK 61316 FJ	1
165	NEWMAR VINYL CASEMENT	M.ENS	SCREENS-REPLA	19.0625 X		1
			CEMENT-WINDO	47.125		1
			WS			

Problem Description: *need Caulking around the Front window exterior.*

☐ Warranty

Material \$

Labour \$

Cause:

☐ CHARGEABLES

Material \$ *157.20*

Labour \$ *120.00*

P.O.#:

Solution:

Date Completed: \_\_\_\_\_

Approved: \_\_\_\_\_

Time: \_\_\_\_\_

Service Signature: \_\_\_\_\_

THARMA

Obj +

A handwritten signature in black ink, appearing to be 'K. J. S.', written over a horizontal line.



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W162391  
Pack Slip:198441

Service Date: Feb 15, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000508 City: WHITBY Received: Jun 24, 2022  
Name: ZANCOR WHITBY Service Phone(s): Time:  
Service Fax: Site Phone: Order: D374344-1  
Site Fax: Lot#: BLK 8 - 46 Phase: PH1

RESIDENT INFORMATION

Home Owner Name: VINOTHAN KUMARAVEL Address:  
Home Phone(s): Work Phone(s):  
Cell Phone(s): 647-991-8376 Email(s): vinothan68@gmail.com

LINKED ORDER INFORMATION (D374344-1)

Customer: N000508 ZANCOR WHITBY Lot #: BLK 8 - 46  
Model: TH-1 Phase: PH1

SERVICE INSTRUCTIONS

- EXTERIOR- PORCH-SCRATCH ON LEFT MULIN AT FRONT DOOR  
-LIVING ROOM- WINDOWS-CRACKED OPERATING WINDOW LEFT SIDE  
-FOYER/HALL-WALLS-ADJUST FRONT DOOR  
-MASTER BEDROOM-WALLS-SCREEN NOT INSTALLED THROUGHOUT  
ADD:  
LIVING ROOM- GENERAL- ITEM #8- WINDOWS- BEFORE WINDOW WAS CRACKED WHEN WE CAME HERE BUT THEY FIXED THE GLASS THEY DIDN'T CHANGE THE WINDOW PANE WHICH HAS A CRACK AND THE OPERATING HANDLE THAT IS NOT WORKING  
MASTER ENSUITE- GENERAL- ITEM #13- WINDOWS - THE OPERATING HANDLE IS NOT WORKING  
MASTER ENSUITE- GENERAL- ITEM #14-WINDOWS- FOR THE 2 BEDROOMS THE WINDOWS DO NOT HAVE NET OPERATING HANDLE NOT WORKING

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
106	NEWMAR VINYL CASEMENT	LIV	FRAME ONLY	24 X 62	RIGHT BK 61316 FJ	1
165	NEWMAR VINYL CASEMENT	M.ENS	SCREENS-REPLA CEMENT-WINDO WS	19.0625 X 47.125		1

Problem Description:

☐ Warranty ☐ CHARGEABLES  
Material \$ \_\_\_\_\_ Material \$ \_\_\_\_\_  
Labour \$ \_\_\_\_\_ Labour \$ \_\_\_\_\_  
P.O.#: \_\_\_\_\_

Cause: \_\_\_\_\_

Solution: \_\_\_\_\_

Date Completed: \_\_\_\_\_

Approved: \_\_\_\_\_

Time: \_\_\_\_\_

Service Signature: \_\_\_\_\_

THARMA



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W162391  
Pack Slip:198441  
Service Date: Nov 14, 2022

Priority: Normal Status: SCHEDULED RELEASED  
**BUILDER**  
Customer: N000508 City: WHITBY Received: Jun 24, 2022  
Name: ZANCOR WHITBY Service Phone(s): Time:  
Service Fax: Site Phone: Order: D374344-1  
Site Fax: Lot#: BLK 8 - 46 Phase: PH1

**RESIDENT INFORMATION**

Home Owner Name: VINOTHAN KUMARAVEL Address:  
Home Phone(s): Work Phone(s):  
Cell Phone(s): 647-991-8376 Email(s): vinothan68@gmail.com

**LINKED ORDER INFORMATION (D374344-1)**

Customer: N000508 ZANCOR WHITBY Lot #: BLK 8 - 46  
Model: TH-1 Phase: PH1

**SERVICE INSTRUCTIONS**

- EXTERIOR- PORCH-SCRATCH ON LEFT MULIN AT FRONT DOOR
- LIVING ROOM- WINDOWS-CRACKED OPERATING WINDOW LEFT SIDE
- FOYER/HALL-WALLS-ADJUST FRONT DOOR
- MASTER BEDROOM-WALLS-SCREEN NOT INSTALLED THROUGHOUT

**ADD:**

LIVING ROOM- GENERAL- ITEM #8- WINDOWS- BEFORE WINDOW WAS CRACKED WHEN WE CAME HERE BUT THEY FIXED THE GLASS THEY DIDN'T CHANGE THE WINDOW PANE WHICH HAS A CRACK AND THE OPERATING HANDLE THAT IS NOT WORKING

MASTER ENSUITE- GENERAL- ITEM #13- WINDOWS - THE OPERATING HANDLE IS NOT WORKING

MASTER ENSUITE- GENERAL- ITEM #14-WINDOWS- FOR THE 2 BEDROOMS THE WINDOWS DO NOT HAVE NET OPERATING HANDLE NOT WORKING

**PARTS REQUIRED**

LN	Item Description	Location	Specification	Size	Options	Qty
106	NEWMAR VINYL CASEMENT	LIV	FRAME ONLY	24 X 62	RIGHT BK 61316 FJ	1
165	NEWMAR VINYL CASEMENT	M.ENS	SCREENS-REPLA	19.0625 X		1
			CEMENT-WINDO	47.125		
			WS			

Problem Description: H/O requested to be rescheduled

☐ Warranty

Material \$ \_\_\_\_\_

Labour \$ \_\_\_\_\_

☐ CHARGEABLES

Material \$ \_\_\_\_\_

Labour \$ \_\_\_\_\_

P.O.#:

Cause: \_\_\_\_\_

Solution: \_\_\_\_\_

Date Completed: 11-14-2022

Approved: \_\_\_\_\_

Time: \_\_\_\_\_

Service Signature: \_\_\_\_\_

*[Signature]*  
JULIO ~~ALEX~~



**Zancor Homes (Parkview) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date:** 30Jun22

**Address:**

**Location:** Now Towns In Brooklin - Phase: 1 - Lot: Unit 46 (Block 8)

**Today's Date:** 24Aug22

**Contact(s):** Vinothan Kumaravel - Cell: (647) 991-8376 - (vinothan68@gmail.com)

**Email:** vinothan68@gmail.com

**Company:** Newmar

**Attention:** Alex

**Telephone:** (905) 672-1233

**Fax:** (905) 672-6350

**Please Complete the following items:**

DAI	Type	Issue		Appt. Date/Time	Notes
148256	PDI	EXTERIOR- PORCH~SCRATCH ON LEFT MULIN AT FRONT DOOR		02Sep22 /am	
148258	PDI	LIVING ROOM- WINDOWS~CRACKE D OPERATING WINDOW LEFT SIDE		02Sep22 /am	
148259	PDI	FOYER/HALL- WALLS~ADJUST FRONT DOOR		02Sep22 /am	
148264	PDI	MASTER BEDROOM- WALLS~SCREEN NOT INSTALLED THROUGHOUT		02Sep22 /am	
149549	30-Day	Living Room- General- item #8- windows- before window was cracked when we came here but they fixed the glass they didn't change the window pane which has a crack and the		02Sep22 /am	

		operating handle that is not working			
149554	30-Day	Master Ensuite-General- item #13- windows - the operating handle is not working		02Sep22 /am	
149555	30-Day	Master Ensuite-General- item #14- windows- for the 2 bedrooms the windows do not have net operating handle not working		02Sep22 /am	

Date Completed: \_\_\_\_\_

Homeowner Signature: \_\_\_\_\_

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: \_\_\_\_\_

**Trade &/or Service Tech.**

Signature: \_\_\_\_\_

Print Name: \_\_\_\_\_


Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**



**Now Towns In Brooklin - Phase: 1 - Lot: Unit 46 (Block 8)**

**148256 - 1 - PORCH~SCRATCH ON LEFT MULIN  
AT FRONT DOOR**



**148258 - 1 - WINDOWS~CRACKED OPERATING  
WINDOW LEFT SIDE**



**148259 - 1 - WALLS~ADJUST FRONT DOOR**



**148264 - 1 - WALLS~SCREEN NOT INSTALLED  
THROUGHOUT**





NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7030 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W162391  
Pack Slip: 198441

Service Date: Aug 24, 2022

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: N000508

City: WHITBY

Received: Jun 24, 2022

Name: ZANCOR WHITBY

Service Phone(s):

Time:

Service Fax:

Site Phone:

Order: D374344-1

Site Fax:

Lot#: BLK 8 - 46

Phase: PH1

RESIDENT INFORMATION

Home Owner Name: VINOTHAN KUMARAVEL

Address:

Home Phone(s):

Work Phone(s):

Cell Phone(s): 647-991-8376

Email(s): vinothan68@gmail.com

LINKED ORDER INFORMATION (D374344-1)

Customer: N000508 ZANCOR WHITBY

Lot #: BLK 8 - 46

Model: T11-1

Phase: PH1

SERVICE INSTRUCTIONS

- EXTERIOR- PORCH-SCRATCH ON LEFT MULIN AT FRONT DOOR *done*

- LIVING ROOM- WINDOWS-CRACKED OPERATING WINDOW LEFT SIDE *order*

- FOYER/HALL-WALLS-ADJUST FRONT DOOR *done*

- MASTER BEDROOM-WALLS-SCREEN NOT INSTALLED THROUGHOUT *done*

Problem Description: *Living Room OP Window Frame Broken*

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$

Labour \$

Labour \$

P.O.#:

Cause:

*order OP window frame size 24X62 RH*

Solution:

Date Completed: *Aug 24-2022*

Approved: \_\_\_\_\_

Time: \_\_\_\_\_

Service Signature: \_\_\_\_\_

*Zaher*  
ZAHER  
*6/11*



Zancor Homes (Parkview) Ltd.  
Warranty Services  
Phone: (905) 738-7010  
Fax: (905) 738-5948

## Work Order

Closing Date: 30Jun22

**Address:**

**Location:** Now Towns In Brooklin - Phase: 1 - Lot: Unit 46 (Block 8)

**Today's Date:** 18Jul22

**Contact(s):** Vinothan Kumaravel - Cell: (647) 991-8376 - (vinothan68@gmail.com)

**Email:** vinothan68@gmail.com

**Company:** Newmar

**Attention:** Alex

**Telephone:** (905) 672-1233

**Fax:** (905) 672-6350

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
148256	PDI	EXTERIOR- PORCH~SCRATCH ON LEFT MULIN AT FRONT DOOR			
148258	PDI	LIVING ROOM- WINDOWS~CRACKED OPERATING WINDOW LEFT SIDE			need caulking around the window exterior.
148259	PDI	FOYER/HALL- WALLS~ADJUST FRONT DOOR			
148264	PDI	MASTER BEDROOM- WALLS~SCREEN NOT INSTALLED THROUGHOUT			

Date Completed: \_\_\_\_\_

Homeowner Signature: Tommy K

The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

Date Completed: Feb 15 23

Trade &/or Service Tech.

Signature: Tharma


Print Name: Tharma

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, It is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.


**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

**Now Towns In Brooklin - Phase: 1 - Lot: Unit 46 (Block 8)**

**148256 - 1 - PORCH~SCRATCH ON LEFT MULIN  
AT FRONT DOOR**



**148258 - 1 - WINDOWS~CRACKED OPERATING  
WINDOW LEFT SIDE**



**148259 - 1 - WALLS~ADJUST FRONT DOOR**



**148264 - 1 - WALLS~SCREEN NOT INSTALLED  
THROUGHOUT**




Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.


**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

**Now Towns In Brooklin - Phase: 1 - Lot: Unit 46 (Block 8)**

**148256 - 1 - PORCH~SCRATCH ON LEFT MULIN  
AT FRONT DOOR**



**148258 - 1 - WINDOWS~CRACKED OPERATING  
WINDOW LEFT SIDE**



**148259 - 1 - WALLS~ADJUST FRONT DOOR**



**148264 - 1 - WALLS~SCREEN NOT INSTALLED  
THROUGHOUT**

