



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W174986

Pack Slip:208000

Service Date: Feb 15, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: N000582 City: BRAMPTON Received: Jan 03, 2023
Name: ZANCOR BRAMPTON Service Phone(s): 416-791-9866 Time: PM
Service Fax: Site Phone: 416-566-5475 Order: D375523-1
Site Fax: Lot#: 15 Phase:

RESIDENT INFORMATION

Home Owner Name: SAHIL AHMAD Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): 647-4493820 Email(s): khadija0308@hotmail.com

LINKED ORDER INFORMATION (D375523-1)

Customer: N000582 ZANCOR BRAMPTON Lot #: 15
Model: 36-5 / OPT.5B / RR.UPG (WOB) (SL) Phase:

SERVICE INSTRUCTIONS

INSTALL MISSING SCREEN IN BED2

Complete

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
191	NEWMAR VINYL CASEMENT	B2	SCREENS-REPLA	19.0625 X		1
			CEMENT-WINDO	55.125		
			WS			

Problem Description: *Dropped off Front Door* *Not home*

☐ Warranty

☐ CHARGEABLES

Material \$ _____

Material \$ *NIC*

Labour \$ _____

Labour \$ _____

P.O.#:

Cause: _____

Solution: _____

Date Completed: *Feb 15/23*

Approved: _____

Time: *15 min*

Service Signature: *[Signature]*

STEVE



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W174986
Pack Slip:208000

Service Date: Feb 15, 2023

Priority: Normal Status: **SCHEDULED**

BUILDER

Customer:	N000582	City:	BRAMPTON	Received:	Jan 03, 2023
Name:	ZANCOR BRAMPTON	Service Phone(s):	416-791-9866	Time:	PM
Service Fax:		Site Phone:	416-566-5475	Order:	D375523-1
Site Fax:		Lot#:	15	Phase:	

RESIDENT INFORMATION

Home Owner Name:	SAHIL AHMAD	Address:	
Home Phone(s):		Work Phone(s):	
Cell Phone(s):	647-4493820	Email(s):	khadija0308@hotmail.com

LINKED ORDER INFORMATION (D375523-1)

Customer:	N000582 ZANCOR BRAMPTON	Lot #:	15
Model:	36-5 / OPT.5B / RR.UPG (WOB) (SL)	Phase:	

SERVICE INSTRUCTIONS

INSTALL MISSING SCREEN IN BED2

PARTS REQUIRED

LN	Item Description	Location	Specfication	Size	Options	Qty
191	NEWMAR VINYL CASEMENT	B2	SCREENS-REPLA CEMENT-WINDO WS	19.0625 X 55.125		1

Problem Description: _____

<input type="checkbox"/> Warranty	<input type="checkbox"/> CHARGEABLES
Material \$ _____	Material \$ _____
Labour \$ _____	Labour \$ _____
	P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____ Approved: _____

Time: _____ Service Signature: _____

STEVE



Zancor Homes (Brampton) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 18Aug22

Address:

Location: Reserve Of Country Trails - Phase: 1 - Lot: 15

Today's Date: 13Dec22

Contact(s): Sahil Ahmad - Cell: (647) 449-3820 Work: (905) 598-3500

Khadija - (khadija0308@hotmail.com)

Areeba Safdar

Email: khadija0308@hotmail.com

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
153013	Interval	Bedroom 2- General- mesh missing at window			

Date Completed: _____

Homeowner Signature: _____

The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: Feb 15/23

Trade &/or Service Tech.

Signature: 

Print Name: Steven Maia

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Reserve Of Country Trails - Phase: 1 - Lot: 15

153013 - 1 - IMG-20221213-WA0000 - mesh missing
at window



153013 - 2 - IMG-20221213-WA0001 - mesh missing
at window

