



Quality Sterling Group

Mike

REPAIR ORDER
722481



BC

BUILDER: Zancor Homes

JOB SITE: Caledon Club

Customer Code:

Job Number: 16338 Board Area:8

COMPLAINT DATE: 11/17/22

LOT: 57A

INSTALLER:

SCHEDULED DATE: 11/25/22

OWNER NAME:

OWNER TEL:

8-1pm

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE: E-MAIL

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

ORIGINAL WO#: 704755

REPAIR DESC: bedroom 4- bubble in carpet

bedroom 2- adjust shim

principal- tuck carpet hump

Also
Raise carpet to ceramic
at 2 doorways

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

not home

Michael Cole
23rd January 2023

INSTALLER'S SIGNATURE:

L. Gode

SUPER'S/OWNER'S SIGNATURE:


[Signature]

DATE: 11/29/22

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



CLASS 1
EXPLOSION
PROTECTION



CLASS 2
FLAME
PROTECTION



CLASS 3
GAS
Compressed Gas



CLASS 4
FLAME
Flammable and
combustible
material



CLASS 5
FLAME
Oxidizing
material



CLASS 6
SKULL AND
CROSSBONES
Materials being
hazardous to
health or
environment



CLASS 7
SKULL AND
CROSSBONES
Materials being
hazardous to
health or
environment



CLASS 8
BIOHAZARD
Infectious Material



CLASS 9
RADIOACTIVE
Corrosive
Material



CLASS 10
RADIOACTIVE
Dangerously
Radioactive
Material

INSTALLER SIGNATURE

DATE