

Robert Cioffi

From: Alexandria Damianidis <Alexandria@zancorhomes.com>
Sent: Wednesday, March 1, 2023 7:48 AM
To: Robert Cioffi; Gisella Fiore
Subject: RE: Kitchen drawer

Hey Rob,

See below

37W

**Deficiencies on Belle Aire Shores - 3 - 37W
For New Image Kitchens**

DAI	Type	Issue	Appt. Date / Time	Notes
154041	Interval	Kitchen- General- when opening drawers, they are all opening	24Feb23 am	
154338	Interval	Kitchen- General- Chip at bottom gable strip edge at upper left cabinet left of hoodfan - Remove black sticker mark from inside cabinet	24Feb23 am	
154131	Interval	Master Ensuite- General- chipped back gable	24Feb23 am	
154130	Interval	Powder Room- General- broken wood below sink	24Feb23 am	
152766	PDI	BEDROOM 2 ENSUITE- VANITY CABINETS~LARGE GAP BETWEEN GABLE AND WALL AT LOWER LEFT CABINET INSIDE AND SHELF NOT STRAIGHT	24Feb23 am	
152765	PDI	BEDROOM 3 ENSUITE- VANITY CABINETS~SMALL CHIP BELOW LEFT SINK AT GABLE	24Feb23 am	
152770	PDI	KITCHEN- CABINETS~CHIP AT UPPER LEFT GABLE LEFT OF HOODFAN BY DRYWALL. 2) SHELF NOT INSTALLED AT LOWER LEFT CABINET LEFT OF HOOFAN RIGHT OF SLIDING DOOR AND AT ALL BOTTOM CABINETS 3) CHIP INSIDE UPPER LEFT CABINET BY DRYWALL INSIDE LOWER GABLE SHELF EDGE 4) CHIP AT UPPER RIGHT GABLE RIGHT OF HOODFAN CORNER 5) TOUCH UP RIGHT GABLE AT STOVE AREA SCRATCHED 6) ADJUST RIGHT LOWER CABINET RIGHT OF STOVE 7) CHIP AT FILLER GABLE BELOW SINK RIGHT SIDE BELOW COUNTERTOP	24Feb23 am	
152773	PDI	MASTER ENSUITE BATH- VANITY CABINETS~CHIP BELOW KICKPLATE BELOW SINK	24Feb23 am	
152774	PDI	MASTER ENSUITE BATH- VANITY CABINETS~H.O REQUESTING SHIM BELOW SINK TO BE REPALCED	24Feb23 am	

From: Robert Cioffi <rcioffi@newimagekitchens.ca>
Sent: March 1, 2023 7:35 AM
To: Gisella Fiore <Gisella@zancorhomes.com>

MARIANO