

Location Data 18 Jun 23

Address: Belle Aire Shores - Phase: 3 - Lot: 37W
Location: 27 Mar 23
Today's Date:
Contact(s): Mariano, Valdez Villalba - Home: (647) 829-9065 - (marianovillalba@gmail.com)
Mariano, B Villalba - Home: (416) 627-0159 - (matbvill1@gmail.com)
Email: marianovillalba@gmail.com

Service by Zancor - Innisfil Warranty Service

Attention:
Telephone:
Fax:

Please Complete the following Items:

DAI	Type	Issue	Appt. Date/Time	Notes
154363	Interval	Master Ensuite- General- Crack between wall and ceiling above toilet room	28 Mar 23 /am	Redirect to FOREMAN
154359	Interval	Shared Bathroom- General- Crack above door trim from entrance to bath between wall and ceiling	28 Mar 23 /am	" "
154362	Interval	Shared Bathroom- General- crack between wall and ceiling in front of tub	28 Mar 23 /am	" "
154363	Interval	Bedroom 4- General- Touch up drywall left of wall at entrance to bath from bedroom and between ceiling and wall	28 Mar 23 /am	" "
154365	Interval	Upper Hall- General- Touch up drywall above stairs between	28 Mar 23 /am	" "

155123	30-Day	ceiling and wall cracked	✓	28Mar23 /am	SAME AS 155180
155140	30-Day	Bedroom 3- General- Item #8 deep gouge in the left facing wall - svc at arch right side Family Room- General- Item #25 improperly finished areas on the wall and corners of the bumpout above fireplace		28Mar23 /am	
155178	30-Day	Stairs- General- Item #62 on the ceiling above stairs leading to 2nd floor, edge of wall/ceiling is not painted properly (has yellow hue)	✓	28Mar23 /am	REDIRECT TO FORUMONT
155180	30-Day	Bedroom 3- General- Item #64 Imperfection on ceiling near big window where there is a discontinuity in the wall - svc at cathedral right side	✓	28Mar23 /am	
155183	30-Day	Den- General- Item #67 bubbled paint beside window on upper right corner	✓	28Mar23 /am	
155192	30-Day	Main Hall- General- Item #76 main hall, 2nd floor - wall has unsmooth paint and there appears to be a dent	✓	28Mar23 /am	
155201	30-Day	Bedroom 5- General- Item #85 wall where computer desk is, near carpet/trim there is a gray marking	✓	28Mar23 /am	
155206	30-Day	Main Hall- General- Item #89 entrance to laundry room - there is	✓	28Mar23 /am	

155208	30-Day	a wide gap between wall and tile Master Ensuite- General- Item #91 multiple problems, gap between the wall and cabinet. some leftover green tape underneath wall, sandwiched between the wall and floor. wide gap. scratches on wall, not smooth - left to door, right vanity	28Mar23 /am ✓
155211	Interval	Bedroom 2- General- unknown cut out for vent left over	28Mar23 /am ✓
155215	Interval	Other- General- inspect gap left of mudroom trim/tile	28Mar23 /am ✓
155241	Interval	Basement- General- Svc to inspect cut out in basement right of furnace-filled with insulation	28Mar23 /am ✓
155246	Interval	Foyer- General- Svc to fill gap at nosing above main floor stairs(Nosing for railing above) Can see from standing at main floor	28Mar23 /am ✓

Date Completed: MAR 23, 23

Homeowner Signature: [Signature]
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: MAR 28/23

Trade &/or Service Tech.

Signature: [Signature]

Print Name: KOENIG

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form