

Closing Date: 15Sep22

Address:

Location: Belle Alre Shores - Phase: 3 - Lot: 31W

Today's Date: 23Nov22

Contact(s): Nicholas, W Johnson - Home: (905) 252-5072 - (nickwj106@gmail.com)

Email: Anne, C Stewart - Home: (905) 252-4835 - (cookingwithease@rogers.com)

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
150045	PDI	EXTERIOR- RAILING-TRIM IN BETWEEN FRONT DOOR SCRATCHED	28Oct22 /day	
152499	30-Day	Exterior- General- Item #31 doors - front door jam between doors has marks	08Dec22 /am	
152502	Interval	Foyer- General- fixed glass at front door left side upper scratched	08Dec22 /am	

Date Completed: Feb 1 - 2023

Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: Jan Feb 1 - 2023

Trade &/or Service Tech.

Signature:

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP
7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W167330
Pack Slip:210313
Service Date: Feb 01, 2023

Priority: Normal

STATUS: SCHEDULED

RELEASED

BUILDER

Customer: 611313

City: INNISFIL

Received: Sep 14, 2022

Name: ZANCOR BELLE AIRE SHORES

Service Phone(s):

Time: 1ST CALL

Service Fax:

Site Phone:

Order: D379231-1

Site Fax:

Lot#: 31W

Phase: 3

RESIDENT INFORMATION

Home Owner Name: NICHOLAS W JOHNSON, ANNE C STE

Address:

nickwj106@gmail.com,

Home Phone(s): 905-252-5072, 905-252-4835

Work Phone(s):

cookingwithease@rogers.com

Cell Phone(s):

Email(s):

LINKED ORDER INFORMATION (D379231-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES

Lot #: 31W

Model: 50-07 DELTA ST+OP GF(LOFT)/DW

Phase: 3

SERVICE INSTRUCTIONS

EXTERIOR- RAILING-TRIM IN BETWEEN FRONT DOOR SCRATCHED--DONE
ADD-
EXTERIOR- GENERAL- DOORS - FRONT DOOR JAM BETWEEN DOORS HAS MARKS--DONE
ADD-
FOYER- GENERAL- FIXED GLASS AT FRONT DOOR LEFT SIDE UPPER SCRATCHED

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
171	5' 8" CLAD DOOR SYS asterical capping , vinyl cladding COMPLETED	ENT	OTHER RPLOMNT PARTS	70.5 X 81.75	DW 61316 FJ RIGHT 5' 8" CLAD DOOR SYS	1
342	220C_STYLE DOORLITE CUSTOM COMPLETED	ENT	DOORLITES ONLY	22 X 48	220C_STYLE DOORLITE CUSTOM AG AG23 DW/WH LOWE_ARG 3T/19/3T	2
515	NEWMAR VINYL TRANSOM	ENT	GLASS ONLY - FIXED	33.125 X 33.875	AG22 DW/WH LOWE_ARG DW	1

Problem Description:

☐ Warranty

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

130

120

Cause:

Replace Transom glass done

Solution:

Date Completed: Feb 1 - 2023

Approved: X

Angela



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP
7030 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G8
TEL (905) 672-1233 FAX (905) 672-1076

WO # W167330
Pack Slip:210313
Service Date: Dec 05, 2022

Priority: Normal
BUILDER
Customer: 611313
Name: ZANCOR BELLE AIRE SHORES
Service Fax:
Site Fax:
Status: SCHEDULED
City: INNISFIL
Service Phone(s):
Site Phone:
Lot#: 31W
Received: Sep 14, 2022
Time:
Order: D379231-1
Phase: 3
RELEASED

RESIDENT INFORMATION

Home Owner Name: NICHOLAS W JOHNSON, ANNE C STE
Home Phone(s): 905-252-5072, 905-252-4835
Cell Phone(s):
Address:
Work Phone(s):
Email(s):
nickwj106@gmail.com,
cookingwithease@rogers.com

LINKED ORDER INFORMATION (D379231-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES
Model: 50-07 DELTA ST+OP GF(LOFT)/DW

Lot #: 31W
Phase: 3

SERVICE INSTRUCTIONS

EXTERIOR- RAILING-TRIM IN BETWEEN FRONT DOOR SCRATCHED - complete
ADD-
EXTERIOR- GENERAL- DOORS - FRONT DOOR JAM BETWEEN DOORS HAS MARKS - complete
FOYER- GENERAL- FIXED GLASS AT FRONT DOOR LEFT SIDE UPPER SCRATCHED


PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
171	5' 8" CLAD DOOR SYS asterical capping , vinyl cladding	ENT	OTHER RPLCMNT PARTS	70.5 X 81.75	DW 61316 FJ RIGHT 5' 8" CLAD DOOR SYS	1
342	220C_STYLE DOORLITE CUSTOM	ENT	DOORLITES ONLY	22 X 48	220C_STYLE DOORLITE CUSTOM AG AG23 DW/WH LOWE_ARG 3T/19/3T	2

Problem Description: Glass upper front door 33 1/4 x 33 3/4 AG 22 /
frame side 35 1/4 x 36

☐ Warranty
Material \$
Labour \$
Cause:

☐ CHARGEABLES
Material \$
Labour \$
P.O.#:



Solution: Perphenide 1 door lite
* Perphenide destroyed (destroyed) complete

Date Completed: Approved:
Time: Service Signature: ALEX