

ZANCOR
HOMES

Zancor Homes (Wasaga) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

0000633
D378037

Closing Date: 21 Oct 22

Address:

25 Beatrice Drive

Wasaga Beach, Ontario

Location: Shoreline Point - Phase: 1 - Lot: 3

Today's Date:

16 Jan 23

Contact(s):

Jasset King - Cell: (416) 795-0986 - (akabiddy@gmail.com)

Email:

akabiddy@gmail.com

Company:

Newmar

Attention:

Alex

Telephone:

(905) 672-1233

Fax:

(905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
151784	Interval	Basement- General- Furnace area window, glass has stress crack	19 Dec 22 /pm	complete
153839	30-Day	Garage- General- Item #16- Gap in Interior garage door is too large. You can feel the air coming inside the house and smell the fumes. You can see the bolt and not enough length to lock the door properly		complete

Date Completed:

Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed:

March 31/23

Trade &/or Service Tech.

Signature:

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no



Priority: Normal Status: SCHEDULED

BUILDER

Customer: N000633 City: WASAGA BEACH Received: Feb 22, 2023

Name: ZANCOR WASAGA SINGLES Service Phone(s): Time: PM

Service Fax: Site Phone: Order: D378037-1

Site Fax: Lot#: 3 Phase:

RESIDENT INFORMATION

Home Owner Name: JASSET KING Address: 25 BEATRICE DRIVE

Home Phone(s): Work Phone(s):

Cell Phone(s): 416-795-0986 Email(s): akabiddy@gmail.com

LINKED ORDER INFORMATION (D378037-1)

Customer: N000633 ZANCOR WASAGA SINGLES Lot #: 3

Model: 52-03 (CB) Phase: Complete

SERVICE INSTRUCTIONS

GAP IN INTERIOR GARAGE DOOR IS TOO LARGE. YOU CAN FEEL THE AIR COMING INSIDE THE HOUSE AND SMELL THE FUMES. YOU CAN SEE THE BOLT AND NOT ENOUGH TO LOCK THE DOOR PROPERLY. FRONT DOOR AND MAN DOOR

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
150	2' 8" WOOD DOOR SYS weather strpping	G/H	OTHER RPLCMNT PARTS	35.25 X 97.75	61316 FJ LEFT 2' 8" WOOD DOOR SYS	1
160	5' 4" CLAD DOOR SYS weather stripping	FOY	OTHER RPLCMNT PARTS	68 X 97.75	CB 61316 FJ LEFT 5' 4" CLAD DOOR SYS	1

Problem Description: H/O Signed Backup

☐ Warranty ☐ CHARGEABLES

Material \$ Material \$ ~~RHC~~

Labour \$ Labour \$

P.O.#:

Cause:

Solution:

Date Completed: March 31/23 Approved:

Time: 3:00pm Service Signature: STEVE