Enrollment:

Phone Res:

Purchaser Name: Dina Imaeva

ZANCOR HOMES PDI

Page 1 of 2

Vendor / Builder:

Project: Zancor Homes (Wasaga) Ltd.

Lot / Phase: 101 / 1
Plan:

Address:

Municiaplity: Inspection Date: April 18, 2023

Phone Bus: (647) 786-9497 **Closing Date:** April 27, 2023

Inspector: Alexandria Damianidis

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

BEDROOM 2 ENSUITE		
VANITY CABINETS	INSPECT CRACKED BACK GABBLE AT PLUMBING	
FOYER/HALL		
STAIRS	SAND, FILL CHIPS AND STAIN NOSING FROM FOYER TO FIRST LANDING 2) SAND AND STAIN NOSING FROM MAIN FLOOR TO GARAGE DOOR LANDING	
	CHIP ON 4TH TREAD FROM MAIN FLOOR TO GARAGE DOOR LANDING 2) BIG CHIP ON 3RD TREAD FROM MAIN FLOOR TO GARAGE DOOR LANDING 3) CHIP AT STRINGER FROM MAIN FLOOR TO GARAGE DOOR LANDING 4) EXPOSED SCREWS BELOW NOSING FROM BMST TO GARAGE DOOR LANDING	
BASEMENT		
WINDOWS	WINDOW NOT INSTALLED IN BASEMENT	
NOTE:	REPLACE CRACKED WOOD LEFT OF GARAGE HOSE BIB AT POLY 2)REMOVE NAILS	
MASTER ENSUITE BATH		
FAUCETS/PLUMBING	2ND SINK STOPPER NOT WORKING	
FAMILY ROOM		
FLOORING	CHIP ON 20TH HARDWOOD PLANK FROM WINDOW	
KITCHEN		
CABINETS	CHIPS ON 2ND UPPER SHELF LEFT OF OVEN CUT OUT 2) CHIP ON UPPER SHELF LEFT OF OVEN CUT OUT 3) RED PEN MARK ON UPPER SHELF RIGHT OF OVEN CUT OUT 4) CHIP INSIDE CORNER CABINET GABLE 5) CHIP/MARK INSIDE OF CORNER CABINET BOTTOM GABLE 6) SCRATCH/DENT ON BANK OF DRAWERS LEFT OF OVEN CUT OUT TOP DRAWER 7) REMOVE GLUE ON LEFT CABINET UNDER SINK	
POWDER ROOM		
NOTE:	DOOR NOT SHUTTING ADJUST	
LAUNDRY ROOM		
NOTE:	FAN MAKING LOUD NOISE	
BEDROOM 4 ENSUITE		
VANITY CABINETS	BACK GABLE CUT OUT MESSY IN BASEMENT WASHROOM	

Enrollment:
Purchaser Name: Dina Imaeva

Phone Res:

Phone Bus: (647) 786-9497

Closing Date: April 27, 2023

Inspector: Alexandria Damianidis

ZANCOR HOMES

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Wasaga) Ltd.

Lot / Phase: 101 / 1 Plan:

Address: Municiaplity:

Inspection Date: April 18, 2023

A REFERENCE FOR FUTURE WAR	RANTY REQUESTS. o designate someone to conduct the PDI in th	E HOME'S CONDITION BEFORE THE PURCHASS neir place should ensure they provide written auth	
I have inspected my new home and	I agree that the description of the items listed	on this form are accurate.	
Dina Imaeva	Gmaer 3		
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Alexandria Damianidis	
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/04/18	April 18, 2023	