



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W179181

Pack Slip:222530

Service Date: Apr 21, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Feb 23, 2023
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D380374-1
Site Fax: Lot#: 78W Phase: 3

RESIDENT INFORMATION

Home Owner Name: N/A Address: N/A
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D380374-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 78W
Model: 42-06 MASTHEAD/DW Phase: 3

SERVICE INSTRUCTIONS

BASEMENT LOOK-OUT FULL OPERATOR. PANE CLOSEST IN CENTER OF UNIT → complete.

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
274	NEWMAR VINYL CASEMENT	ADD- LOB	SASH AND GLASS	28.125 X 28.125	RIGHT DW CLR LOWE_ARG	1

Problem Description: Complete

☐ Warranty

Material \$

Labour \$

☒ CHARGEABLES

Material \$ 108

Labour \$ 120

P.O.#:

Cause: Builder to clean exterior windows. BASEMENT. MB
Living Room.

Solution: INSTALLED SASH

Date Completed: Apr 21/23

Approved: [Signature]

Time: 20 mins

Service Signature: RICHARD

2/23/23, 2:34 PM

Newmar / Casa Bella Mail - Lot 78w



Service Department <servicedept@newmar.com>

Lot 78w


1 message

Nathan Simas <nathan@zancorhomes.com>

Tue, Feb 21, 2023 at 2:18 PM

To: Service Department <servicedept@newmar.com>

Basement look-out full operator
Pane closest in center of unit



2/23/23, 2:34 PM

Newmar / Casa Bella Mail - Lot 78w

Thanks,

Nathan Simas

Finishing Supervisor

Now Towns in Brooklin / Belle Aire Shores

Cell # 416-791-9862

nathan@zancorhomes.com