Enrollment:

Phone Res:

Purchaser Name: Surej Pabla

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 17B / 1B

Plan: Address:

Municiaplity:

Inspection Date: April 24, 2023

Phone Bus: (647) 459-0060 **Closing Date:** February 09, 2023

Inspector: Gisella Fiore Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH		
VANITY CABINETS	CHIP INSIDE BOTTOM RIGHT AND LEFT GABLE AT SINK	
FAUCETS/PLUMBING	SINK STOPPER NOT HOLDING WATER LEFT SIDE	
NOTE:	OVER CUT AT WALL TILE INSIDE SHOWER AT FACUET.	
FLOORING	ADJUST SHIM AT ENTRANCE TO BATHROOM.	
MAIN BATHROOM		
VANITY CABINETS	CHIP INSIDE ALL 4 CABINET BELOW SINK AT SCREW HOLES OF HANDLES	
BEDROOM #4		
WINDOWS	CRACKED FIXED GLASS UPPER RIGHT.	
FOYER/HALL		
STAIRS	VARNISH SPLATTERS ON 3RD RISER AT STAIRS FROM MAIN FLOOR TOO 2ND FLOOR	
	DAMAGE NOSING BELOW TRIM LEFT SIDE AT ENTRANCE FROM GARAGE.	
WINDOWS	ADJUST MAN DOOR	
KITCHEN		
CABINETS	CHIP AT RIGHT GABLE AT ISLAND FACING BREAKFAST AREA 2) CHIP AT BOTTOM RIGHT AND	
	LEFT CABINET AT ISLAND FACING LIVING. 3) CHIP AT UPPER RIGHT CABINET RIGHT OF HOOD	
	FAN. 4) CHIP AT UPPER GABLE ABOVE HOOD FAN 5) CHIP INSIDE BOTTOM CABINET LEFT OF GARBAGE DRAWER AT BOTTOM GABLE	
	VISIBLE SEAM AT CROWN MOULDING. NO FINISH ON CROWN AND BOX. 2) CHIP AT UPPER	
	CROWN LEFT CORNER LEFT OF HOODFAN.	
ELECTRICAL/LIGHTING	HOOD FAN COVER NOT INSTALLED.	
LAUNDRY ROOM		
NOTE:	CHIP INSIDE BOTTOM GABLE LEFT SIDE BELOW SINK.	
DINING ROOM		
TRIM	DOOR STOP NOT INSTALLED AT LAUNDRY DOOR.	
EXTERIOR		

Enrollment:
Purchaser Name: Surej Pabla

Phone Res:

Phone Bus: (647) 459-0060

Closing Date: February 09, 2023
Inspector: Gisella Fiore

ZANCOR HOMES PDI

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 17B / 1B

Plan: Address: Municiaplity:

Inspection Date: April 24, 2023

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Surej Pabla Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Gisella Fiore Designate's Signature Inspector's Name (print) Designate's Name (print) Inspector's Signature Date (YYYY/MM/DD) 2023/04/24 April 24, 2023