



Quality Sterling Group

REPAIR ORDER
734990



NC

BUILDER: Zancor Homes

JOB SITE: Belle Aire Shores PH3

Customer Code:

Job Number: 18648 Board Area:8

COMPLAINT DATE: 03/17/23

LOT: 41W

INSTALLER:

SCHEDULED DATE: 03/31/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE: E-MAIL

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

ORIGINAL WO#: 716432

REPAIR DESC: ADJUST CARPET SHIM AT ENTRANCE TO MAIN BATH AND BELOW WINDOW. BEDROOM 2 AND BEDROOM 3

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE: [Signature]

SUPER'S/OWNER'S SIGNATURE: [Signature]

DATE: 3/31/23

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



HEAD
PROTECTION



PROTECTION



CLASS A
Compressed
Gas



CLASS B
Flammable and
combustible
material



CLASS C
Oxidizing
material



CLASS D
Corrosive
material



CLASS D
Toxic material



CLASS D
Infectious Material



CLASS E
Corrosive
Material



CLASS F
Flammable
Material

INSTALLER SIGNATURE

DATE

Carpet Service


From: Gisella Fiore <Gisella@zancorhomes.com>
Sent: Monday, March 20, 2023 2:47 PM
To: Carpet Service; Patrick Fazari
Cc: Alexandria Damianidis
Subject: LOT 41W Innisfil-FOLLOW UP-QSG

EXTERNAL SENDER

Good Afternoon
Has this been completed yet

Deficiencies on Belle Aire Shores - 3 - 41W For Quality Rugs Canada LTD.

DAI	Type	Issue	Appt. Date / Time	Notes
153267	PDI	BEDROOM #3- FLOORING~ADJUST CARPET SHIM AT ENTRANCE TO MAIN BATH AND BELOW WINDOW TO BE SECURED IN BEDROOM 2 AND BEDROOM 3	17Mar23 am	



Gisella Fiore
Service Manager
Gisella@zancorhomes.com
P: 905.738.7010 F: 905.738.5948
221 North Rivermede Road- Concord, ON L4K 3N7

CONFIDENTIALITY NOTICE: This email message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential and privileged information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, please reply to the sender by email and destroy all copies of the original message.



CUTTING SHEET COPY



716432
INSTALL

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



HEAD PROTECTION



FOOT PROTECTION



CLASS A
Compressed
Gas



CLASS B
Flammable and
combustible
material



CLASS C
Oxidizing
material



CLASS D
Materials causing
immediate and
serious toxic
effects



CLASS D
Materials causing
other toxic effects



CLASS D
Bio hazardous
Infectious Material



CLASS E
Corrosive
Material



CLASS F
Dangerously
Reactive
Material

INSTALLER SIGNATURE _____

DATE _____

Created by: Irscheduling 2022-10-03 07:56:00
Printed by: cservicesched 2023-03-23 12:10

IMPORTANT
IF YOU HAVE A PROBLEM CALL

Page: 1 of 1



Quality Sterling Group

REPAIR ORDER
734990



NC

BUILDER: Zancor Homes

JOB SITE: Belle Aire Shores PH3

Customer Code:

Job Number: 18648 Board Area:8

COMPLAINT DATE: 03/17/23

LOT: 41W

INSTALLER:

SCHEDULED DATE: 03/31/23

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION: 0

ACCESS NOTES:

REPAIR TYPE: E-MAIL

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

ORIGINAL WO#: 716432

REPAIR DESC: ADJUST CARPET SHIM AT ENTRANCE TO MAIN BATH AND BELOW WINDOW. BEDROOM 2 AND BEDROOM 3

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE: [Signature]

SUPER'S/OWNER'S SIGNATURE: [Signature]

DATE: 3/31/23

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

INSTALLER SIGNATURE

DATE



HEAD PROTECTION



FEET PROTECTION



CLASS A
Compressed
Gas



CLASS B
Flammable and
combustible
material



CLASS C
Oxidizing
material



CLASS D
Corrosive
material



CLASS E
Toxic material



CLASS F
Infectious Material



CLASS G
Corrosive
Material



CLASS H
Dangerous
Reactive
Material