

Sterling Group

*** PREVIEW USE ONLY *** REPAIR ORDER

731165



PO

Gerry Mike

BUILDER: Zancor Homes

JOB SITE: Caledon Club

Customer Code:

Job Number: 18338 Board Area:8

COMPLAINT DATE: 02/16/23

LOT: 117A

INSTALLER:

SCHEDULED DATE: 02/23/23

OWNER NAME: Kirandeep Kaur Dhaliwal - Jask

OWNER TEL: 9057823441

OWNER ADDR:

kiranbath20@gmail.com

647741-5912 kiranbath20@gm

ACCESS NOTES:

REPAIR DURATION: 0

REPAIRMAN:

REPAIR TYPE: E-MAIL

BUILDER PO#: TBC

BUILDER WO#

PO Required: YES Inspection Req'd: NO

ORIGINAL WO#: 704549

REPAIR DESC: Master Bedroom General- vent cut out missing in carpet . PK20754

PROD INFO/NOTES: Opening Night/TXP140 - 04 PK20754

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

*Also remove faulty underpad.
at Bed 3*

INSTALLER'S SIGNATURE: *Phil Cole*

SUPER'S/OWNER'S SIGNATURE: *J S R*

DATE: 02/23/2023

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



HEAD
PROTECTION



FOOT
PROTECTION



CLASS A
Compressed
Gas



CLASS B
Flammable and
combustible
material



CLASS C
Oxidizing
material



CLASS D
Materials causing
immediate and
serious toxic
effects



CLASS D
Materials causing
other toxic effects



CLASS D
Bio hazardous
material



CLASS E
Corrosive
Material



CLASS F
Dangerously
Reactive
Material

INSTALLER SIGNATURE

DATE