Enrollment:

Purchaser Name: Ashwani Aggarwal

Madhu Aggarwal

Phone Res:

Phone Bus: (647) 624-5336 Closing Date: July 04, 2023

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 25B / 1B

Plan: Address: Municiaplity:

Inspection Date: May 01, 2023

Inspector: Alexandria Damianidis Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

EXTERIOR			
PAINT	PAINTING NOT COMPLETE AT HARDYBOARD		
FOYER/HALL			
FRONT DOORS	SCREW COVER PLATE NOT INSTALLED		
STAIRS	CRACK AT 7TH STRINGER AT STAIRS FROM MAIN TO 2ND FLOOR		
	VARNISH DRIPS ON 4TH AND 5TH TREAD AT STAIRS FROM MAIN TO 2ND FLOOR		
	HOMEOWNER REQUESTING TO INSPECT STAIRS AT MAIN FLOOR, NOT STRAIGHT		
MASTER ENSUITE BATH			
COUNTERTOPS	INSPECT BLACK SCRATCH BESIDE RIGHT SINK		
VANITY CABINETS	CHIP ON LEFT CABINET DOOR BELOW RIGHT SINK		
UPPER HALL			
NOTE:	ADJUST CLOSET DOOR, HARD TO OPEN AND CLOSE		
MASTER BEDROOM			
FLOORING	INSPECT BROWN MARK AT ENTRANCE TO CLOSET		
BEDROOM #3			
FLOORING	ADJUST CARPET SHIM AT ENTRANCE TO BATHROOM		
BEDROOM 3 ENSUITE			
VANITY CABINETS	CHIP AT BOTTOM GABLE BELOW SINK		
KITCHEN			
CABINETS	CHIP AT RIGTH AND LEFT ISLAND GABLE 2) CHIP AT UPPER CORNER GABLE FILLER RIGHT OF		
	HOODFAN 3) CHIP IN UPPER RIGHT GABLE AT HOOD FAN 4) CHIP AT IUPPER LEFT GABLE		
	INSIDE LKEFT CABINET ST FRIDGE 5) CHIP INSIDE 2ND POT DRAWER LEFT OF STOVE 6) CHIP		
	AT SHELF INSIDE CORNER CABINET LEFT OF FRIDGE		
LAUNDRY ROOM			
CABINETS	FILLER PIECES NOT INSTALLED AT UPPER CABINETS RIGHT AND LEFT SIDE 2) CHIP AT FILLER		
	PIECE BELOW SINK 3) CHIP INSIDE UPPER LEFT CABINET INSIDE SHELF		
LIVING ROOM			
FLOORING	SCRATCH ON 9TH AND 10TH PLNK FROM DINNING ROOM WINDOW 2) SCRATCH ON 3,4 AND 18TH		
	HARDWOODS PLANK AT ENTRENCE FROM MUDROOM		

Enrollment:

Purchaser Name: Ashwani Aggarwal

Madhu Aggarwal

Phone Res:

Phone Bus: (647) 624-5336
Closing Date: July 04, 2023
Inspector: Alexandria Damianidis



Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 25B / 1B

Plan: Address: Municiaplity:

Inspection Date: May 01, 2023

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.  * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.							
I have inspected my new home and I agree that the description of the items listed on this form are accurate.							
	1 M						
Ashwani Aggarwal	14.	Madhu Aggarwal					
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature				
		Alexandria Damianidis	AD				
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature				
Date (YYYY/MM/DD)	2023/05/01	May 01, 2023					