



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP
7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G8
TEL (905) 872-1233 FAX (905) 872-1076

WO # W182778
Pack Slip: 226693
Service Date: May 09, 2023

Priority: Normal

BUILDER

Customer: N000531

Name: ZANCOR CALEDON CLUB

Service Fax:

Site Fax:

RESIDENT INFORMATION

Home Owner Name:

Home Phone(s):

Cell Phone(s):

LINKED ORDER INFORMATION (D385024-1)

Customer: N000531 ZANCOR CALEDON CLUB

Model: RLTH-02 HIGHLAND (BK)

SERVICE INSTRUCTIONS

WARPED SASH LN#72

ADD

FAMILY ROOM WINDOW IS BOWING AND WILL NOT CLOSE

SITE ACCESS AT TRAILER

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
72	NEWMAR VINYL CASEMENT	FRT/REC	SASH AND GLASS	22.125 X 58.125	LEFT BK AG13 LOWE_ARG	1

Problem Description:

☐ Warranty

Material \$

Labour \$

Cause:

Replaced window sash - done

Solution:

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Date Completed: May 9-2023

Approved: X

Time:

Service Signature:

ZAHED

Edu