



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP
7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W182923
Pack Slip:222231
Service Date: May 09, 2023

Priority: Normal

BUILDER

Customer: N000531

City: CALEDON

Name: ZANCOR CALEDON CLUB

Service Phone(s):

Service Fax:

Site Phone: BLK149-5

Site Fax:

Lot#: BLK149-5

Received: Apr 05, 2023

Time:

Order: D385445-1

Phase:

RESIDENT INFORMATION

Home Owner Name: N/A

Address: N/A

Home Phone(s):

Work Phone(s):

Cell Phone(s):

Email(s):

LINKED ORDER INFORMATION (D385445-1)

Customer: N000531 ZANCOR CALEDON CLUB

Lot #: BLK149-5

Model: RLTH-02 HIGHLAND (CB)

Phase:

SERVICE INSTRUCTIONS

- BEDROOM 2: GENERAL ADJUST OPERATING WINDOW HITTING SEAL WHEN OPENING *done*
- RIPPED SCREEN AT SLIDING DOOR BY KITCHEN *done*
- LIVING ROOM: SETTLEMENT CRACK AT UPPER RIGHT FIXED GLASS ABOVE OPERATING WINDOW. *done*

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
123	NEWMAR VINYL PICTURE WINDOW	GRT	GLASS ONLY - FIXED	57.875 X 9.875	CLR LOWE_ARG SIM 2-PART CB	1
160	BUCKINGHAM PURCH. PATIO DOOR	BKF	SCREENS-REPLA CEMENT-DOORS	35.375 X 92.375	CB 61316 LEFT BUCKINGHAM PURCH. PATIO DOOR	1

Problem Description:

☐ Warranty

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Replaced transom glass adjust windows replaced screen

done

Solution:

Date Completed: *May 9, 2023*

Approved: *X [Signature]*

Time:

Service Signature: *[Signature]*
ZAHNER