



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W180526
Pack Slip:234285

Service Date: May 12, 2023

Priority: Normal Status: **SCHEDULED** RELEASED

BUILDER

Customer: 611313 City: INNISFIL Received: Mar 10, 2023
Name: ZANCOR BELLE AIRE SHORES Service Phone(s): Time:
Service Fax: Site Phone: Order: D390415-1
Site Fax: Lot#: 244W Phase: 3

RESIDENT INFORMATION

Home Owner Name: Address: *1640 CORSAL COURT*
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (D390415-1)

Customer: 611313 ZANCOR BELLE AIRE SHORES Lot #: 244W
Model: 50-05 BREAKER/SW Phase: 3

SERVICE INSTRUCTIONS

BLUE CIRCLE SHOWS THE CRACK IN THE OUTSIDE PANE *done*

REAR MAIN FLOOR FIXED GLASS *done*

ADD:
MB-130 WINDOW GLASS BROKEN ON H/L OPERATOR (DOUBLE OPERATOR) 120X48 *done*

**THE DOOR WILL BE OPEN. **

ADD
REPLACE IG UNIT ON LINE: 121 (MENS)

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
112	NEWMAR VINYL CASEMENT FIXED	FAM	GLASS ONLY - FIXED	24.75 X 50.75	CLR LOWE_ARG SW	<i>3</i> <i>done</i>
132	NEWMAR VINYL CASEMENT FIXED	MB	GLASS ONLY - FIXED	24.75 X 42.75	CLR LOWE_ARG SW	1
251	NEWMAR VINYL CASEMENT FIXED Replace the glass	MENS	GLASS ONLY - FIXED	24.75 X 34.75	CLR LOWE_ARG SW	1

Problem Description: *BROKEN*

Warranty CHARGEABLES
Material \$ _____ Material \$ *284*
Labour \$ _____ Labour \$ *120*
P.O.#: _____

Cause: _____

Solution: *REPLACEMENT OF 3 WINDOWS*

*NOTE: NO ONE AVAILABLE FOR SIGNATURE
(NO BODY AT THE BUILDERS TRAILOR)*

Date Completed: _____

Approved: _____

Time: 12:50 - 1:35

Service Signature: _____



RAY



Manjot Singh <msingh@newmar.com>

WO # W180526

1 message

Mathew Harant <mharant@newmar.com>
To: Manjot Singh <msingh@newmar.com>

Wed, May 3, 2023 at 12:46 PM

Hi Manjot,

Can you please add to this SWO:

Replace IG unit on line: 121 (MENS)

Thank you,

Mathew Harant
Sales Account Manager

Newmar Window Manufacturing Inc.

7630 Airport Road
Mississauga, Ontario L4T 4G6
Tel: 905-672-1233
Fax: 905-672-1076
Toll Free: 1-800-263-5634
www.newmar.com

Click here for information on Newmar Aluminum Window Wall systems

Manufacturers of Quality Windows and Entrance Door Systems

Please consider the environment before printing this email.

This e-mail and any attachments may contain information that is privileged and/or confidential. If you are not the intended recipient and appear to have received this e-mail in error, please notify us immediately and then delete all copies from your computer system. Any unauthorized use, copying or further distribution is prohibited. Please also note that if you send us e-mails containing time-sensitive or important instructions, you should ensure that receipt has been timely acknowledged in view of the potential for misdirection or inadvertent interception. Thank you.



Service Department <servicedept@newmar.com>

Lot 244

1 message

Nathan Simas <nathan@zancorhomes.com>
To: Service Department <servicedept@newmar.com>

Wed, Mar 8, 2023 at 1:33 PM

Blue circle shows the crack in the outside pane

Rear main floor fixed glass

Thanks,

Nathan Simas
Finishing Supervisor
Now Towns in Brooklin / Belle Aire Shores
Cell # 416-791-9862
nathan@zancorhomes.com

2 attachments



processed-5f607a48-c48d-49d1-9f0b-702255cb30ed_iZFdbpoq.jpeg
5176K



output-9a373034-cd75-4bd5-9f99-d9cfb7e9ab92_hYkm5ZAO.jpeg
1477K