Enrollment:

Purchaser Name: ???????

Ramani Vimaleswaran

Phone Res:

Phone Bus: (905) 781-4038 **Closing Date:** June 08, 2023

ZANCOR HOMES PDI Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 126B / 1B

Plan: Address: Municiaplity:

Inspection Date: May 29, 2023

Inspector: Gisella Fiore Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

EXTERIOR		
NOTE:	RIPPED TARP ON RIGHT SIDE OF HOUSE AND REAR OF HOME	
BRICKS	MOTOR REQUIRED AT BRICK BELOW SLIDING DOOR.	
	CRACK IN FOUNDATION. WALL RIGHT SIDE OF SIDE ENTRANCE CONDUCT WATER TEST.	
	LEDGE NOG INSTALLED BELOW SIDE ENTRANCE DOOR.	
FOYER/HALL		
STAIRS	CHIP ON NOSING AT LANDING TO GARAGE.	
	SHOE NOT FLUSH TO FLOOR HITTING TREAD AT STAIRS TO LANDING TO 2ND FLOOR.	
	STAIN REQUIRED AT NOSING AT LANDING.	
POWDER ROOM		
NOTE:	CHIP AT BOTTOM GABLE BELOW SINK.	
SINK/FAUCET/PLUMBING	UPGRADED BATHROOM ACCESSORIES NOT INSTALLED THROUGHOUT.	
KITCHEN		
COUNTERTOPS	BACKSPLASH NOT INSTALLED.	
CABINETS	CHIP INSIDE UPPER GABLE ABOVE FRIDGE.	
	FILL NAIL HOLES AT CROWN MOULDING THROUGHOUT.	
	SMALL CHIP AT UPPER RIGHT CABINET LEFT OF FRIDGE.	
	CHIP AT 2ND BANK OF DRAWER LEFT OF STOVE	
	CHIP AT UPPER RIGHT CABINET LEFT OF HOODFAN AND RIGHT GABLE RIGHT OF HOODFAN.	
	CHIP ON LEFT ISLAND STRIP FACING BREAKFAST.	
	UPPER GABLE AT LEFT SIDE OF HOODFAN FACING BREAKFAST BUBBLED INSIDE CABINET AND	
	OUTSIDE LEFT SIDE.	
NOTE:	DENT ON SLIDING DOOR TRACK RIGHT SIDE	
BASEMENT		
NOTE:	DUCTS NOT CLEANED.	

Enrollment:

Purchaser Name: ???????

Ramani Vimaleswaran

Phone Res:

Phone Bus: (905) 781-4038
Closing Date: June 08, 2023
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Inspector's Signature

Lot / Phase: 126B / 1B

Plan: Address: Municiaplity:

Inspection Date: May 29, 2023

MASTER ENSUITE BATH		
NOTE:	CHIP ON MARBLE SURROUND AT BASE ENTRANCE TO SHOWER.	
VANITY CABINETS	CHIP AT BOTTOM GABLE BELOW RIGHT SINK.	
MASTER BEDROOM		
FLOORING	ADJUST CARPET SHIM AT ENTRANCE TO WASHROOM.	

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Ramani Vimaleswaran

Purchaser's Name (print) Purchaser's Signature

Purchaser's Signature

Purchaser's Name (print) Purchaser's Signature

Gisella Fiore

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Date (YYYY/MM/DD)

2023/05/29

May 29, 2023