



Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 25Nov22

Address:

Location: Caledon Club - Phase: 1 - Lot: 57A

Today's Date: 17Nov22

Contact(s):

Email:

Company: Newmar

Attention: Alex

Telephone: (905) 672-1233

Fax: (905) 672-6350

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
152290	PDI	LIVING ROOM- WINDOWS-CIRCLE CRACK ON LEFT FIXED WINDOW		✓
152299	PDI	BEDROOM #4- WINDOWS-SCRATC H ON UPPER RIGHT FIXED GLASS ABOVE OPERATING AT BED ROOM ABOVE PORCH		✓
152307	PDI	MASTER BEDROOM- WINDOWS-SMALL CHIP AT UPPER LEFT CORNER FIXED WINDOW		✓
152312	PDI	MASTER ENSUITE BATH- WALLS-SCREEN ON WINDOW NOT INSTALLED		MR
152315	PDI	FOYER/HALL- FRONT DOORS-ADJUST		✓

OPERATING DOOR

Date Completed: 12/01/2023 Homeowner Signature: [Signature]
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: 12/01/23 Trade &/or Service Tech. [Signature]
Signature: [Signature]
Print Name: R E Y

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP
7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W172614
Pack Slip:210678
Service Date: Feb 13, 2023

Priority: Normal

BUILDER

Customer: N000531

Name: ZANCOR CALEDON CLUB

Service Fax:

Site Fax:

Status:

City: CALEDON

Service Phone(s):

Site Phone:

Lot#: 57A

SCHEDULED

Received: Nov 18, 2022

Time:

Order: D380142-1

Phase:

RESIDENT INFORMATION

Home Owner Name:

Home Phone(s):

Cell Phone(s): 647-267-9521

Address: CALEDON CLUB - PHASE: 1 / 6 CALABRIA DRI

Work Phone(s):

Email(s): fineabhay@gmail.com, chetana.bafana@gmail.com

LINKED ORDER INFORMATION (D380142-1)

Customer: N000531 ZANCOR CALEDON CLUB

Model: 30-05 CAPILANO (STND + OPT. GROUND) (BK)

Lot #: 57A

Phase:

- SERVICE INSTRUCTIONS
- LIVING ROOM- WINDOWS-CIRCLE CRACK ON LEFT FIXED WINDOW
- 152299 - BEDROOM #4- WINDOWS-SCRATCH ON UPPER RIGHT FIXED GLASS ABOVE OPERATING AT BED ROOM ABOVE PORCH
- 152307 - MASTER BEDROOM- WINDOWS-SMALL CHIP AT UPPER LEFT CORNER FIXED WINDOW
- 152312 - MASTER ENSUITE BATH- WALLS-SCREEN ON WINDOW NOT INSTALLED
- 152315 - FOYER/HALL- FRONT DOORS-ADJUST

ADD:
MAIN HALL - WINDOW IS NOT PROPERLY SQUARE
FOYER - SCREW COVER IS MISSING (INTERIOR)

PARTS REQUIRED				
LN	Item Description	Location	Specification	Size Options Qty
21	NEWMAR VINYL CASEMENT FIXED crack on glass COMPLETED	DIN/FAM	GLASS ONLY - FIXED	18.75 X 62.75 CLR LOWE_ARG BK 1
143	NEWMAR VINYL PICTURE WINDOW SCRATCH ON GLASS COMPLETED	B3	GLASS ONLY - FIXED	21.875 X 15.875 CLR LOWE_ARG BK 1
221	NEWMAR VINYL CASEMENT	ENS	SCREENS-REPLA CEMENT-WINDO WS	25.0625 X 43.125 1

Problem Description: No Repair Backup

☐ Warranty

☐ CHARGEABLES

Material \$

Labour \$

Material \$ 176

Labour \$ 120

P.O.#:



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6
TEL (905) 672-1233 FAX (905) 672-1076

WO # W172614
Pack Slip: 210678
Service Date: Jan 13, 2023

Priority: Normal

Status: SCHEDULED

RELEASED

BUILDER

Customer: N000531

City: CALEDON

Received: Nov 18, 2022

Name: ZANCOR CALEDON CLUB

Service Phone(s):

Time:

Service Fax:

Site Phone:

Order: D380142-1

Site Fax:

Lot#:

57A

Phase:

RESIDENT INFORMATION

Home Owner Name:

Address:

CALEDON CLUB - PHASE: 1 / 6 CALABRIA DRI

Home Phone(s):

Work Phone(s):

Cell Phone(s): 647-267-9521

Email(s): fineabhay@gmail.com,

chetana.bafana@gmail.com

LINKED ORDER INFORMATION (D380142-1)

Customer: N000531 ZANCOR CALEDON CLUB

Lot #: 57A

Model: 30-05 CAPILANO (STND + OPT. GROUND) (BK)

Phase:

SERVICE INSTRUCTIONS

LIVING ROOM- WINDOWS-CIRCLE CRACK ON LEFT FIXED WINDOW

152299 - BEDROOM #4- WINDOWS-SCRATCH ON UPPER RIGHT FIXED GLASS ABOVE OPERATING WINDOW ABOVE PORCH

152307 - MASTER BEDROOM- WINDOWS-SMALL CHIP AT UPPER LEFT CORNER FIXED WINDOW

152312 - MASTER ENSUITE BATH- WALLS-SCREEN ON WINDOW NOT INSTALLED - MR. 30x42

152315 - FOYER/HALL- FRONT DOORS-ADJUST

PARTS REQUIRED

LN Item Description

Location

Specification

Size

Options

Qty

21 NEWMAR VINYL CASEMENT FIXED
crack on glass

DIN/FAM

GLASS ONLY -
FIXED

18.75 X 62.75

CLR LOWE_ARG BK

1

143 NEWMAR VINYL PICTURE WINDOW
SCRATCH ON GLASS

B3

GLASS ONLY -
FIXED

21.875 X 15.875

CLR LOWE_ARG BK

1

Problem Description:

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$

Labour \$

Labour \$

Cause:

P.O.#:

Solution:

Date Completed:

Approved: